

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000533/KGS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900156670
Claimant Vehicle No :	SLD8803J	Insured Vehicle No :	SMN9507T
Date of Loss:	11/01/2021	Nature of Claim:	TP
		Claim No:	7535058293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8803J		
Make & Model:	VOLKSWAGEN GOLF, 1.4 A7 TSI AT BMT 5G14JZ SR	Engine No:	CZC415310
Reg. Date:	30/06/2016 (Man. Year: 2015)	Chassis No:	WVWZZZAUZGW083140
Colour:	Metallic Grey	Odometer:	69571 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,562.50	2,306.70	4,255.80	64.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	995.00	2,135.00	68.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,692.50	3,301.70	6,390.80	65.94
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	9,692.50	2,600.00	7,092.50	73.18
+ GST 7.00/7.00% (S\$)	678.48	182.00	496.48	73.18
Nett Amount (S\$)	10,370.98	2,782.00	7,588.98	73.18
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,212.00		

INSPECTION

Date of Assignment:	12/01/2021		
Date Inspected:	28/01/2021	Inspected At:	MBM Wheelpower Pte Ltd (Sin Ming) 176 Sin Ming Drive #01-15, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	850.00 FL	*- FL
2	1		*TAILGATE	Bent	2,000.00 FL	*1,450.00 FL
3	1		*TAILGATE WEATHERSTRIP	Serviceable	360.00 FL	*- FL
4	1		*TAILGATE HINGE LH	Repair	120.00 FL	*- FL
5	1		*TAILGATE HINGE RH	Repair	120.00 FL	*- FL
6	1		*TAILGATE LOCK	Repair	240.00 FL	*- FL
7	1		*TAILGATE VOLKSWAGON LOGO	Serviceable	130.00 FL	*- FL
8	1		*TAILGATE GOLF EMBLEM	Necessary	110.00 FL	*88.00 FL
9	1		*TAILGATE TSI EMBLEM	Necessary	75.00 FL	*75.00 FL
10	1		*TAILGATE LAMP LH	Serviceable	190.00 FL	*- FL
11	1		*TAILGATE LAMP RH	Serviceable	190.00 FL	*- FL
12	1		*TAIL LAMP LH	Serviceable	300.00 FL	*- FL
13	1		*TAIL LAMP RH	Serviceable	300.00 FL	*- FL
14	1		*REAR BUMPER	Buckled / Cracked	850.00 FL	*850.00 FL
15	1		*REAR BUMPER REINFORCEMENT	Repair	420.00 FL	*- FL
16	1		*REAR BUMPER RETAINER LH	Serviceable	75.00 FL	*- FL
17	1		*REAR BUMPER RETAINER RH	Serviceable	75.00 FL	*- FL
18	1		*REAR BUMPER TOWING COVER	Serviceable	30.00 FL	*- FL
19	1		*REAR BUMPER REFLECTOR LH	Serviceable	50.00 FL	*- FL
20	1		*REAR BUMPER REFLECTOR RH	Serviceable	50.00 FL	*- FL
21	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
22	1		*REAR BUMPER SENSOR	Serviceable	220.00 FL	*- FL
23	1		*REAR BUMPER LOWER SPOILER	Serviceable	320.00 FL	*- FL
24	1		*REAR NUMBER PLATE & HOLDER	Cracked	100.00 FS	*45.00 FS
25	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,275.00	2,558.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	712.50	251.30
Total Parts (\$\$)	6,562.50	2,306.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,600.00	400.00
2	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	100.00	15.00
3	TO REMOVE & REFIT ALL SENSOR	New	100.00	50.00
4	TO REALIGN EXHAUST PIPE	New	50.00	0.00
5	TO APPLY ANTI RUST COATING	New	80.00	30.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	500.00
Gross Labour Cost (\$\$)			3,130.00	995.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >