



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5568K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER,REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY,REAR BUMPER	BENT	332.70	332.70
1	GUARD,REAR BUMPER,CENTER	BENT	374.50	374.50
1	COVER REAR BUMPER TOWING	DENTED	22.00	22.00
1	RETAINER,REAR BUMPER SIDE,LH	NO SUCH PARTS	132.60	-
1	RETAINER,REAR BUMPER SIDE,RH	NO SUCH PARTS	132.60	-
1	SEAL,REAR BUMPER SIDE,RH	SERVICEABLE	118.30	-
1	PANEL SUB-ASSY,BACK DOOR	TO REPAIR SEE LABOUR	1,147.80	-
1	GARNISH SUB-ASSY,BACK DOOR OUTSIDE	TO REPAIR SEE LABOUR	913.60	-
1	STAY ASSY,BACK DOOR,LH	SERVICEABLE	242.50	-
1	STAY ASSY,BACK DOOR,RH	SERVICEABLE	242.50	-
1	HINGE ASSY,BACK DOOR,LH	TO REPAIR SEE LABOUR	61.00	-
1	HINGE ASSY,BACK DOOR,RH	TO REPAIR SEE LABOUR	61.00	-
1	ORNAMENT SUB-ASSY,BACK DOOR	NECESSARY	47.90	47.90
1	PLATE,LUGGAGE COMPARTMENT DOOR NAME,NO 2	NECESSARY	54.60	54.60
1	PLATE,BACK DOOR NAME,NO 1	NECESSARY	54.60	54.60
	LESS 25% DISCOUNT		-1,105.95	-342.97
			3,317.85	1,028.93
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	85.00	66.00
1	BUMPER CENTRE GUARD CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	30.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	180.00	30.00
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	200.00	-

Report Ref No. CS/AGI21000543/Kvf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	130.00	-
			1,760.00	156.00
	LABOUR			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,BACK DOOR,GARNISH SUB-ASSY,BACK DOOR OUTSIDE,HINGE ASSY,BACK DOOR,LH AND HINGE ASSY,BACK DOOR,RH.		1,600.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	400.00
	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	300.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
			4,840.00	660.00
GRAND TOTAL			9,917.85	1,844.93
RECOMMENDED COST OF REPAIRS				1,844.93

Report Ref No. CS/AGI21000543/Kvf3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.