



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|-----------------------|-----------------------------|------------|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS/SMO21000546/DKtd3n2 | |
| | | | Date: 05/07/2021 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBD 3879S | Veh. Inspected | SHD 3333D |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | CMTD2100123/AGC | Excess (\$) | 0.00 |
| | Assign From | GRACE TEO | Assign Date | 12/01/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | HYUNDAI I40 | c.c | 1685 |
| | Engine No. | HIDDEN | Year of Reg. | 2016 |
| | Chassis No. | KMHLB41UMGU092164 | Colour | BLUE |
| | Odometer | 783496 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 205/60 R16 | WEST LAKE | 5 mm |
| | L/H Front Tyre | 205/60 R16 | WEST LAKE | 5 mm |
| | R/H Rear Tyre | 205/60 R16 | WEST LAKE | 5 mm |
| | L/H Rear Tyre | 205/60 R16 | WEST LAKE | 5 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 09/01/2021 | Inspection Date | 12/01/2021 |
| | Survey held at | BLK 9 SECTOR C# 01-42 | | |
| | Repairer | BIFROST AUTO PTE LTD | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 7 Working Days | |