



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8784H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | SCRATCHED | 688.00 | 688.00 |
| 1 | BUMPER REFLECTOR RHS | SERVICEABLE | 95.00 | - |
| 8 | REAR BUMPER CLIPS @\$3.00 | NECESSARY | 24.00 | 24.00 |
| | LESS 10% DISCOUNT | | -80.70 | -71.20 |
| | | | 726.30 | 640.80 |
| LABOUR | | | | |
| | TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT/EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON THE AFFECTED AREAS & COMPONENTS WITH OVEN SPRAY BOOTH FACILITIES. | | 600.00 | 200.00 |
| | TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE,INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS;JACK,PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS,CORRECT & REALIGN THE NECESSARY PARTS. | | 400.00 | 200.00 |
| | | | 1,000.00 | 400.00 |
| GRAND TOTAL | | | 1,726.30 | 1,040.80 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 800.00 |

Report Ref No. CS/SMO21000547/R1Ktf3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.