



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDJ 303B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR RH	BENT	2,185.00	2,185.00
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	985.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	2,650.00	-
1	REAR BUMPER	* CHECK	2,050.00	-
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	100.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	150.00	-
1	REAR ALLOY RIM RH	DENTED	1,820.00	1,820.00
	LESS 10% DISCOUNT		-994.00	-400.50
			8,946.00	3,604.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	* CHECK	50.00	-
1	REAR TYRE TUBE VALVE RH (SN)	NECESSARY	15.00	15.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SCRATCHED	350.00	350.00
			495.00	365.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE,REFIX,REPLACE & READJUST REAR ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF ROCKER PANEL RH AND REAR FENDER RH.		1,000.00	600.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH,REAR FENDER RH,ROCKER PANEL RH,REAR BUMPER & ETC.		1,000.00	660.00
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR RH INNER MECHANISM & ETC.BACK TO ORIGINAL OPERATIONS.		120.00	60.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS,REAR WINDSCREEN SEALANT,REAR WINDSCREEN MOULDING & ETC.TO EFFECT REPLACE OF REAR FENDER RH.	NOT NECESSARY	120.00	-
	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM,INNER COVERING RH,REAR PILLAR TRIM RH & ETC.TO EFFECT REPLACE OF REAR FENDER RH.		150.00	100.00

Report Ref No. CS/AGI21000548/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC.		100.00	20.00
	TO WHEEL ALIGNMENT & BALANCING.		80.00	60.00
	TO TUFF KOTE & UNDERSEAL MATERIALS.		150.00	20.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		120.00	20.00
			2,840.00	1,540.00
GRAND TOTAL			12,281.00	5,509.50
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,895.00 NETT)				5,509.50

Report Ref No. CS/AGI21000548/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.