LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG21000549/EVF3E2

AIG Building, 78 Shenton Way #07-16

Singapore 079120 Date: 02/02/2021

REFERENCE

Insured/Claimant: LEW YEE KEONG LAWRENCE Policy No: 2070136307

Date of Loss: 10/01/2021 Nature of Claim: OD Claim No: 4148277136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMV1950G

Make & Model: KIA NIRO, 1.6 HYBRID GDI DCT SUNROOF (A) Engine No: G4LEKS600328

Reg. Date: 21/09/2020 (Man. Year: 2019) Chassis No: KNACC81CVL5361060

Colour: Red Odometer: 5802 km

Engine Capacity: 1580 cc
Market Value/New Car Price: \$\$106,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts | | 3,446.00 | 2,174.40 | 1,271.60 | 36.90 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 1,030.00 | 1,030.00 | 0.00 | 0.00 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 4,476.00 | 3,204.40 | 1,271.60 | 28.41 |
| | - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| | (S\$) | 3,876.00 | 2,604.40 | 1,271.60 | 32.81 |
| | + GST 7.00/7.00% (S\$) | 271.32 | 182.31 | 89.01 | 32.81 |
| | Nett Amount (S\$) | 4,147.32 | 2,786.71 | 1,360.61 | 32.81 |

INSPECTION

Date of Assignment: 12/01/2021

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

Date Inspected: 12/01/2021 Inspected At: 209 Pandan Gardens

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE Manager: VERON CHEN

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---|--------------|----------------------------------|---------------------|------------|------------|
| 1 | 1 | | *SUNDRY | Necessary | 20.00 FS | *20.00 FS |
| 2 | 1 | | *COVER-FR BUMPER UPR | Broken | 637.00 F | *637.00 FL |
| 3 | 1 | | *LOGO ASSY-KIA SUB | Necessary | 51.00 F | *51.00 FL |
| 4 | 1 | | *COVER-FR BUMPER, LWR | Cut | 373.00 F | *373.00 FL |
| 5 | 1 | | *SKID PLATE-FR BUMPER | Cut | 60.00 F | *60.00 FL |
| 6 | 1 | | *GRILLE ASSY-RADIATOR | Cut | 441.00 F | *441.00 FL |
| 7 | 1 | | *ABSORBER-FRONT BUMPER ENERGY | Not Necessary | 68.00 F | *- FL |
| 8 | 1 | | *LAMP ASSY-FRONT FOG, LH | Broken | 223.00 F | *223.00 FL |
| 9 | 1 | | *COVER-DAYTIME RUNNING LIGHT, LH | Not Necessary | 46.00 F | *- FL |
| 10 | 1 | | *LAMP ASSY-DAY RUNNING LIGHT, LH | Not Necessary | 619.00 F | *- FL |
| 11 | 1 | | *GRILLE-FRONT BUMPER | Cut | 131.00 F | *131.00 FL |
| 12 | 1 | | *STIFFNER-FR BPR LWR | Crushed | 116.00 F | *116.00 FL |
| 13 | 1 | | *BEAM COMPLETE-FR BUMPER | Bent | 661.00 F | *661.00 FL |
| F=Fra | nchise | part. S=SpcN | ett. L=ListItemDisc. | _ | | |
| | | | | Sub Total (S\$) | 3,446.00 | 2,713.00 |
| | - List Item Discount on L Items 0.00/20.00% (S\$) | | | 0.00 | 538.60 | |
| | | | | Total Parts (S\$) | 3,446.00 | 2,174.40 |
| | | | Report was unsubmitted dur | ing this print-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|---|--------------|------------|----------|
| Lab | our Items | | | |
| 1 | RENEW FRT BUMPER LOWER PANEL, FRT BUMPER, FRT SKID PLATE | New | 400.00 | 400.00 |
| 2 | SPRAY PAINT FOR FRT BUMPER, SKID PLATE | New | 480.00 | 480.00 |
| 3 | CHECK WIRING & ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| | Gross Labou | r Cost (S\$) | 1,030.00 | 1,030.00 |
| | Report was unsubmitted during this p | rint-out. | | |

< END OF ESTIMATES >