

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000554/DTD3Q2
Date: 22/03/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001148115
Claimant Vehicle No :	SGG83R	Insured Vehicle No :	GBE2734C
Date of Loss:	19/12/2020	Nature of Claim:	TP
		Claim No:	251864

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG83R	Engine No:	FA20A982368
Make & Model:	SUBARU FORESTER, 2.0 XT CVT AWD SR (A)	Chassis No:	JF1SJGK85GG075535
Reg. Date:	30/08/2016 (Man. Year: 2016)	Odometer:	80474 km
Colour:	White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R18	Rear Tyre Size:	235/45R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,174.40	2,937.84	13,236.56	81.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,550.00	1,000.00	5,550.00	84.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,724.40	3,937.84	18,786.56	82.67
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	22,724.40	3,100.00	19,624.40	86.36
+ GST 7.00/7.00% (S\$)	1,590.71	217.00	1,373.71	86.36
Nett Amount (S\$)	24,315.11	3,317.00	20,998.11	86.36

INSPECTION

Date of Assignment:	12/01/2021		
Date Inspected:	13/01/2021 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047	
Estimated Period of Repair:	3.0 days		

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

3/22/2021

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2021)

Parts: M1-SUV SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGG83R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,890.00 FL	*- FL
2	1		*BONNET INSULATOR	Not Necessary	510.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	390.00 FL	*- FL
4	1		*BONNET CHROME MOULDING	Not Necessary	580.00 FL	*- FL
5	1		*HEAD LAMP LH	Scratched/Mounting Broken	2,940.00 FL	*2,380.10 FL
6	1		*HEAD LAMP LOWER BRACKET LH	Cracked	240.00 FL	*89.50 FL
7	1		*FRONT BUMPER	Cut/Dented	1,995.00 FL	*694.50 FL
8	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	186.00 FL	*- FL
9	1		*FRONT BUMPER LOWER LID	Not Necessary	872.00 FL	*- FL
10	1		*FRONT BUMPER UNDER COVER	Not Necessary	410.00 FL	*- FL
11	1		*FRONT FENDER LH	Dented	1,283.00 FL	*483.20 FL
12	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	210.00 FL	*- FL
13	1		*FRONT WHEEL BEARING LH	Not Necessary	385.00 FL	*- FL
14	1		*FRONT WHEEL BEARING HUB LH	Not Necessary	410.00 FL	*- FL
15	1		*FRONT KNUCKLE ARM LH	Not Necessary	879.00 FL	*- FL
16	1		*FRONT LOWER ARM LH	Not Necessary	582.00 FL	*- FL
17	1		*FRONT ABSORBER LH	Not Necessary	503.00 FL	*- FL
18	1		*FRONT STABILIZER BAR	Not Necessary	499.00 FL	*- FL
19	1		*FRONT STABILIZER LINK LH	Not Necessary	241.00 FL	*- FL
20	1		*FRONT TIE ROD LH	Not Necessary	278.00 FL	*- FL
21	1		*FRONT TIE ROD END LH	Not Necessary	310.00 FL	*- FL
22	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
24	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
25	1		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*SPORT RIM	Not Necessary	2,000.00 FS	*- FS
29	1		*TYRE	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,493.00	3,667.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,318.60	729.46
Total Parts (\$\$)	16,174.40	2,937.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,600.00	400.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,600.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	20.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
5	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT	New	150.00	0.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRING	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			6,550.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >