Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000560/DQD3Q2

**Date:** 28/01/2021

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001623103

Claimant
Whitele No: SKC6027M

Insured Vehicle No: SLT3947B

Vehicle No: SKC6027M Insured Vehicle No: SL13947B

Date of Loss: 11/01/2021 Nature of Claim: TP Claim No: 251966

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKC6027M

 Make & Model:
 MERCEDES-BENZ C180, 1.6 Kompressor (A)
 Engine No:
 27191031346571

 Reg. Date:
 14/09/2011 (Man. Year: 2011)
 Chassis No:
 WDD2040452A587135

Colour: Silver Odometer: 140293 km

Engine Capacity: 1597 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm
Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,073.00	2,386.89	6,686.11	73.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,280.00	1,320.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,673.00	3,666.89	8,006.11	68.59
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	11.673.00	2.900.00	8.773.00	75.16

**INSPECTION** 

Date of Assignment: 12/01/2021

Date Inspected: 13/01/2021 Inspected At: Alfred Auto Services & Supplies (HQ)

Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2

Alig Mo No Ilidusiliai Fa

Singapore 569538

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2021)

Parts: 143 MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC6027M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

Total Parts (S\$) 9,073.00

**Amount** 

2,386.89

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qtv Part No. Particulars

NO.	Qιy	rait No. raiticulais	Condition	Nepallel 5	Amount			
1	1	*REAR BOOT	Repair	1,890.00 F	*- FN			
2	1	*REAR BOOT LOCK	Serviceable	39.00 F	*- FN			
3	1	*REAR BOOT C180 EMBLEM	Serviceable	99.00 F	*- FN			
4	1	*KOMPRESSOR EMBLEM	Serviceable	145.00 F	*- FN			
5	1	*WEATHER SLIP	Serviceable	205.00 F	*- FN			
6	1	*REAR BUMPER	Distorted/Dented	1,550.00 F	*1,312.32 FN			
7	1	*REAR BUMPER REINFORCEMENT	Serviceable	1,178.00 F	*- FN			
8	2	*REAR BUMPER BRACKET CENTR	E Not Necessary	116.00 F	*- FN			
9	1	*REAR BUMPER CENTRE GARNISH	Mounting Cracked	190.00 F	*190.00 FN			
10	2	*REAR BUMPER SIDE GARNISH	Not Necessary	190.00 F	*- FN			
11	1	*REAR BUMPER CENTRE CHROME	Necessary	229.00 F	*164.00 FN			
12	2	*REAR BUMPER SIDE CHROME	Necessary	330.00 F	*230.00 FN			
13	2	*REAR BUMPER SIDE RETAINER	Not Necessary	118.00 F	*- FN			
14	1	*REAR BUMPER INNER HOLDER	N/s Broken	180.00 F	*90.00 FN			
15	1	*EXHAUST CHROME	Serviceable	420.00 F	*- FN			
16	1	*END PANEL	Not Necessary	930.00 F	*- FN			
17	1	*END PANEL GARNISH	Mounting Deformed	388.00 F	*388.00 FN			
18	4	*END PANEL CLIPS	Serviceable	24.00 F	*- FN			
19	1	*PARKING SENSOR (4 Pcs)	N/s Damaged/O/s Not Necessary	792.00 FS	*220.00 FS			
20	10	*BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS			
F=Fra	F=Franchise part. S=SpcNett. N=NettItemDisc.							
			Sub Total (S\$)	9,073.00	2,624.32			
		- Nett Item Disc	count on N Items 0.00/10.00% (S\$)	0.00	237.43			

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & REFIT & CHECK WIRING	New	180.00	30.00
2	TO REPAIR,KNOCKING,STRAIGHTENING & RENEW ALL ACCIDENT DAMAGE AFFECTED AREA	New	900.00	600.00
3	TO RESPRAY PAINTING ON ALL ACCIDENT DAMAGE AFFECTED AREA	New	1,000.00	400.00
4	TO REMOVE & REFIT INTERIOR GARNISH & CARPET	New	160.00	100.00
5	TO RUST PROOF ALL ACCIDENT DAMAGE AFFECTED AREA	New	180.00	0.00
6	TO DIAGNOSTIC CHECK ON ALL SENSOR & ERASE FAULT CODE	New	180.00	150.00
	Gross Labour Cost (S\$)		2,600.00	1,280.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >