

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 27 Jan 2021

Preliminary Advice

Insured Vehicle No	: SLT3947B		
TP Vehicle No	: SKC6027M	Accident Date	: 11/01/2021
Make	: MERCEDES-BENZ C180	Assignment Date	: 12/01/2021
Date of Inspection	: 13/01/2021	Est. Duration of Repair	: 3
Inspection At	: ALFRED AUTO SERVICES & SUPPLIES (HQ) BLK 5035, ANG MO KIO AVE 3, #01-351, ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569538		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,673.00
Revised Amount	:S\$	3,666.89
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,666.89
 Lump Sum Repair	 :S\$	 2,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.