

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 7465R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER RH (CONSISTENT)	BENT	598.00	430.00
1	FRONT FENDER EMBLEM (VVTI) (CONSISTENT)	NECESSARY	120.00	42.20
1	FRONT FENDER INNER SHIELD RH (CONSISTENT)	TORN	215.00	209.10
1	FRONT ABSORBER RH (CONSISTENT)	NOT NECESSARY	398.60	-
1	FRONT LOWER ARM RH (CONSISTENT)	NOT NECESSARY	672.30	-
1	FRONT KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	890.00	-
1	FRONT WHEEL BEARING RH (CONSISTENT)	NOT NECESSARY	289.00	-
1	FRONT DRIVE SHAFT RH (CONSISTENT)	NOT NECESSARY	1,010.00	-
1	FRONT ANTI ROLL BAR LINK RH (CONSISTENT)	NOT NECESSARY	269.80	-
1	FRONT STEERING RICK (CONSISTENT)	NOT NECESSARY	1,154.00	-
1	FRONT ORIGINAL RIM RH (CONSISTENT)	NOT NECESSARY	980.00	-
1	HEAD LAMP RH (CONSISTENT)	CUT	2,999.80	2,999.80
1	HEAD LAMP CHROME RH (CONSISTENT)	NECESSARY	125.00	125.00
2	HEAD LAMP LOWER BRACKET RH@\$68.00 (CONSISTENT)	N/S NOT NECESSARY / O/S CRACKED	136.00	68.00
1	HEAD LAMP TOP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	228.00	-
1	WIPER TANK (CONSISTENT)	DEFORMED	179.00	179.00
1	FRONT BUMPER (CONSISTENT)	DEFORMED	541.00	541.00
2	FRONT BUMPER SIDE RETAINER @\$125.00 (CONSISTENT)	N/S NOT NECESSARY / O/S DEFORMED	250.00	125.00
1	FRONT BUMPER TOP GARNISH (CONSISTENT)	NOT NECESSARY	169.00	-
1	FRONT BUMPER TOP RUBBER (CONSISTENT)	NOT NECESSARY	79.00	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	399.00	399.00
1	FRONT BUMPER SPONGE (CONSISTENT)	DEFORMED	125.00	125.00
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	CRACKED	452.00	298.60
1	FRONT BUMPER FOG LAMP BRACKET RH (CONSISTENT)	CRACKED	155.00	80.00
1	FRONT BUMPER UNDER COVER (CONSISTENT)	TORN	178.00	178.00
	LESS 25% DISCOUNT		-3,153.13	-1,449.93
			9,459.37	4,349.77

Report Ref No. CC4/ASM21000566/T1pa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NECESSARY	40.00	10.00
1	FRONT TYRE LH (SN) (CONSISTENT)	NOT NECESSARY	400.00	-
1	RADIATOR COOLANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			570.00	40.00
	<u>LABOUR</u>			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF HEAD LAMP TOP PANEL RH .		1,400.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	400.00
	TO PERFORM LIGHTING & WIRING CHECK.		100.00	30.00
	TO APPLY ANTI-RUST & TUFF KOTE.		200.00	30.00
	REMOVE AND INSTALL FRONT UNDER CARRIAGE.	NOT NECESSARY	600.00	-
	TO CHECK FOUR WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	ABS LIGHT RESET.	NOT NECESSARY	250.00	-
			4,050.00	860.00
	GRAND TOTAL		14,079.37	5,249.77

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		
·	· ·	

Report Ref No. CC4/ASM21000566/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.