

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21000573/GPA3Q2

Date:

27/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKA135J

Policy No:

Insured Vehicle No :

SLX8586E

Date of Loss: 07/01/2021

Nature of Claim:

TP

Claim No:

1464740568SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKA135J**

Make & Model: MERCEDES-BENZ CLA180, 1.3 COUPE AMG LINE (A)

Reg. Date: 30/03/2020 (Man. Year: 2019)

Colour: Black

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 28291480158154

Chassis No: WDD1183842N007433

Odometer: 14485 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 235/35R19

Front Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Tyre Size:

235/35R19

Rear Left Side:

Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,850.50	5,436.29	10,414.21	65.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	930.00	1,770.00	65.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	18,550.50	6,366.29	12,184.21	65.68
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		

Nett Liability (S\$)	6,901.29
Global Sum Settlement (S\$)	6,800.00

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 13/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ace Chrome Restorations & Automotive (HQ)
2 Kaki Bukit Avenue 2 #02-24 Kaki Bukit Autohub
Singapore 417921

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP O/S	Scratched	4,336.00 FL	*2,987.53 FL
2	1		*HEADLAMP LOWER BRACKET O/S	Not Necessary	185.00 FL	*- FL
3	1		*FRONT BUMPER (AMG)	Broken	1,899.00 FL	*1,378.90 FL
4	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	236.00 FL	*- FL
5	1		*FRONT BUMPER LOGO	Necessary	199.00 FL	*85.00 FL
6	1		*RADIATOR GRILLE (AMG)	Not Necessary	1,616.00 FL	*- FL
7	1		*RADIATOR GRILLE BASE	Not Necessary	615.00 FL	*- FL
8	1		*RADIATOR GRILLE OUTER TRIM	Not Necessary	594.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	795.00 FL	*- FL
10	1		*FRONT BUMPER SIDE GRILLE O/S	Not Necessary	467.00 FL	*- FL
11	1		*FRONT BUMPER SIDE GRILLE SENSOR HOLDER O/S	Not Necessary	48.00 FL	*- FL
12	1		*FRONT BUMPER DIFFUSER (AMG)	Not Necessary	1,243.00 FL	*- FL
13	1		*FRONT BUMPER SPONGE	Not Necessary	287.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	757.00 FL	*- FL
15	1		*FRONT BUMPER SIDE SENSOR HOLDER O/S	Not Necessary	48.00 FL	*- FL
16	12		*FRONT BUMPER CLIPS	Necessary	78.00 FS	*30.00 FS
17	1		*FRONT BUMPER LOWER SPOILER (AMG)	Cut	2,800.00 FS	*1,400.00 FS
18	1		*FRONT BUMPER SIDE PARKING SENSOR O/S	Not Necessary	465.00 FS	*- FS
19	1		*FRONT BUMPER SIDE GRILLE SENSOR O/S	Not Necessary	465.00 FS	*- FS
20	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,183.00	5,881.43
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,332.50	445.14
Total Parts (\$\$)	15,850.50	5,436.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW ACCIDENT DAMAGED PORTIONS,TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	300.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	200.00	30.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	600.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (S\$)			2,700.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >