5/19/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG21000578/R1BA3Q2

Date:

19/05/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

1700045488 SLR8563C

Claimant Vehicle No:

SKC2331K 08/01/2021 Insured Vehicle No: Nature of Claim:

TP

Claim No:

6348323922SG

WAUZZZF43KA110644

CVK087414

12257 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC2331K

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

31/10/2019 (Man. Year: 2019) Reg. Date:

Colour: Grey

Engine Capacity: 1984 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size:

205/60 R16

Front Left Side: Front Right Side: Continental 6 mm Continental 6 mm Rear Left Side:

Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		15,063.00	8,761.12	6,301.88	41.84
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,932.00	2,932.00	2,000.00	40.55
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	19,995.00	11,693.12	8,301.88	41.52
	+ GST 7.00/7.00% (S\$)	1,399.65	818.52	581.13	41.52

Nett Amount (S\$)	21,394.65	12,511.64	8,883.01	41.52
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	13,013.64		

INSPECTION

Date of Assignment: 14/01/2021

Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Date Inspected: 14/01/2021

Inspected At: Singapore 408699

Estimated Period of Repair: 5.0 days

MOHD RASUL Adjuster: Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR BUMPER	Deformed	2,996.00 FS	*2,396.80 FS
2 1	*REAR BUMPER FIXING PARTS	Not Necessary	459.00 FS	*-FS
3 1	*REAR BUMPER SECURIG STRIP	Necessary	223.00 FS	*178.00 FS
4 1	*REAR BUMPER SPOILER	Cut	249.00 FS	*198.80 FS
5 1	*REAR BUMPER TRIM	Cut	292.00 FS	*233.20 FS
6 2	*REAR BUMPER BRACKET -LH/RH	Serviceable	232.00 FS	*-FS
7 2	*REAR LIGHT REFLECTOR -LH/RH	Serviceable	82.00 FS	*-FS
8 1	*LED TAIL LIGHT -LH/RH	N/S Scratched	2,038.00 FS	*815.20 FS
9 2	*TAIL LIGHT TRIM -LH/RH	Serviceable	60.00 FS	*-FS
10 1	*LED LICENSE PLATE LIGHT	Cracked	101.00 FS	*80.80 FS
11 1	*REAR BUMPER CARRIER	Bent	1,063.00 FS	*850.40 FS
12 2	*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*-FS
13 2	*REAR BUMPER GUIDE SECTION -LH/RH	Serviceable	46.00 FS	*-FS
14 2	*REAR BUMPER HOLDING STRAP -LH/RH	Serviceable	166.00 FS	*-FS
15 2	*REAR PARKING AID SENSOR -INNER /OUTER	Serviceable	484.00 FS	*-FS
16 1	*REAR LID	Bent	3,252.00 FS	*2,601.60 FS
17 2	*REAR LID HINGE -LH/RH	Serviceable	458.00 FS	*-FS
18 1	*REAR LID LOCK	Serviceable	230.00 FS	*-FS
19 1	*REAR LID ATTACHMENT PARTS	Not Necessary	411.00 FS	*-FS
20 1	*LID LOCK PUSH BUTTON	Scratched	1,389.00 FS	*1,111.20 FS
21 1	*REAR LID LOCK STRIKER	Serviceable	33.00 FS	*-FS
22 1	*REAR LID FLAP GASKET	Not Necessary	205.00 FS	*-FS
23 1	*PACKING ADHESIVE	Necessary	19.00 FS	*14.88 FS
24 1	*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
25 1	*A4 EMBLEM	Necessary	99.00 FS	*79.04 FS
26 1	*REAR NO PLATE	Scratched	60.00 FS	*60.00 FS
27 1	*SUNDRIES	Necessary	250.00 FS	*31.20 FS
F=Franchise part. S=SpcNet	t.			
		Total Parts (S\$)	15,063.00	8,761.12

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)			2,932.00
	Report was unsubmitted during this print-out.			

< END OF ESTIMATES >