

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG21000582/KPA3Q2

**Date:** 13/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900100759

**Claimant**  
**Vehicle No :** SDJ1899S **Insured Vehicle No :** SML4797R

Date of Loss: 09/01/2021 Nature of Claim: TP Claim No: 4504899975SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDJ1899S</b>	Engine No:	27492030417805
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Chassis No:	WDD2050422R088129
Reg. Date:	17/12/2015 (Man. Year: 2015)	Odometer:	100502 km
Colour:	Metallic Silver		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,240.00	8,846.40	4,393.60	33.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,940.00	1,830.00	2,110.00	53.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,180.00</b>	<b>10,676.40</b>	<b>6,503.60</b>	<b>37.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,050.00</b>		
<b>(S\$)</b>	17,180.00	8,050.00	9,130.00	53.14
<b>+ GST 7.00/7.00% (S\$)</b>	1,202.60	563.50	639.10	53.14
<b>Nett Amount (S\$)</b>	<b>18,382.60</b>	<b>8,613.50</b>	<b>9,769.10</b>	<b>53.14</b>
<b>+ Car Rental (8.0 x S\$140.00/day + 7.00% GST) (S\$)</b>		1,198.40		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>9,813.90</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,800.00</b>		

### INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 12/01/2021 Inspected At:

MBM Wheelpower Pte Ltd (HQ)  
160 Sin Ming Drive #06-02, Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 6.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,200.00 FL	*2,170.00 FL
2	1		*BOOTLID HINGE -LH	Repair	320.00 FL	*- FL
3	1		*BOOTLID HINGE -RH	Repair	320.00 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Dented	198.00 FS	*110.00 FS
5	1		*BOOTLID CHROMESTRIP	Serviceable	200.00 FL	*- FL
6	1		*BOOTLID (C200) EMBLEM	Necessary	125.00 FL	*41.00 FL
7	1		*BOOTLID MERCEDES LOGO	Necessary	95.00 FL	*80.00 FL
8	1		*BOOTLID LOCK	Dented	350.00 FL	*350.00 FL
9	1		*REAR FENDER TOP GARNISH -LH	Cracked	120.00 FL	*120.00 FL
10	1		*REAR FENDER TOP GARNISH -RH	Distorted	120.00 FL	*120.00 FL
11	1		*REAR TAIL LAMP -LH	Mtg Cracked	1,050.00 FL	*805.00 FL
12	1		*REAR TAIL LAMP -RH	Cracked	1,050.00 FL	*805.00 FL
13	1		*REAR TAIL LAMP BRACKET -LH	Repair	105.00 FL	*- FL
14	1		*REAR TAIL LAMP BRACKET -RH	Repair	105.00 FL	*- FL
15	1		*REAR BUMPER RETAINER -LH	Serviceable	95.00 FL	*- FL
16	1		*REAR BUMPER RETAINER -RH	Distorted	95.00 FL	*95.00 FL
17	1		*REAR BUMPER RETAINER -CENTRE	Bent	155.00 FL	*155.00 FL
18	1		*REAR BUMPER	Bent	1,850.00 FL	*1,590.00 FL
19	1		*REAR BUMPER TOWING COVER	Missing	65.00 FL	*65.00 FL
20	10		*REAR BUMPER CLIPS	Necessary	135.00 FS	*60.00 FS
21	1		*REAR BUMPER CHROME STRIP -LH	Necessary	120.00 FL	*120.00 FL
22	1		*REAR BUMPER CHROME STRIP -RH	Necessary	120.00 FL	*120.00 FL
23	1		*REAR BUMPER LOWER SPOILER	Dented	380.00 FL	*380.00 FL
24	1		*REAR BUMPER LOWER COVER -CHROME	Cracked	280.00 FL	*215.00 FL
25	1		*REAR BUMPER REINFORCEMENT	Repair	750.00 FL	*- FL
26	15		*REAR BUMPER RIVET	Necessary (10 PCS ONLY)	135.00 FL	*60.00 FL
27	1		*REAR BUMPER UNDER COVER -RH	Cracked	190.00 FL	*190.00 FL
28	1		*REAR END PANEL	Bent	1,300.00 FL	*1,300.00 FL
29	1		*REAR END PANEL TOP GARNISH	Distorted	135.00 FL	*135.00 FL
30	4		*REVERSE SENSOR	Shorted (2 PCS ONLY)	1,000.00 FS	*472.00 FS
31	1		*BODY SEALANT	Necessary	150.00 FS	*30.00 FS
32	1		*CERAMIC COATING	Not Necessary	750.00 FS	*- FS
33	1		*REAR NUMBER PLATE HOLDER	Serviceable	60.00 FS	*- FS
34	1		*REAR REVERSE CAMERA (50%)	Shorted	300.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,423.00</b>	<b>9,738.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,183.00	891.60
<b>Total Parts (\$\$)</b>	<b>13,240.00</b>	<b>8,846.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	1,600.00	700.00
2	TO REMOVE & REPLACE BUMPER SENSORS	New	120.00	60.00
3	TO REMOVE & INSTALL BOOTLID INNER COMPONENT TO FACILITATE REPAIR	New	100.00	60.00
4	TO REMOVE & REFIT REAR PANEL LINING & GARNISH TO FACILITATE REPAIR	New	120.00	60.00
5	TO REMOVE & INSTALL UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
6	TO APPLY ANTI RUST COATING	New	100.00	30.00
7	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	300.00	0.00
8	TO CHECK & RECONNECT ALL WIRING	New	50.00	20.00
9	TO SPRAY PAINT ON THE AFFECTED AREA	New	1,400.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,940.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >