

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000585/ABS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993857

Claimant
Vehicle No : GBB5737R **Insured Vehicle No :** SLV4173A

Date of Loss: 08/01/2021 Nature of Claim: TP Claim No: 9221494549SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB5737R		
Make & Model:	TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)	Engine No:	1KD1930472
Reg. Date:	24/06/2009 (Man. Year: 2009)	Chassis No:	JTFAT35Y60K200677
Colour:	Silver	Odometer:	186002 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R12
Front Left Side:	APLUS 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	APLUS 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,726.60	7,658.37	8,068.23	51.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,740.00	2,020.00	53.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,486.60	9,398.37	10,088.23	51.77
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	19,486.60	7,500.00	11,986.60	61.51
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,307.45		
Global Sum Settlement (S\$)		8,300.00		

INSPECTION

Date of Assignment: 11/01/2021

Date Inspected: 11/01/2021 Inspected At:

Cn Motors Pte Ltd (HQ)
1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	820.25 F	*589.00 FL
2	1		*FRONT BUMPER BRACKET	Not Necessary	285.00 F	*- FL
3	1		*FRONT GRILLE	Cracked	581.45 F	*581.45 FL
4	8		*FRONT GRILLE CLIP	Not Necessary	52.00 F	*- FL
5	1		*FRONT GRILLE LOGO	Not Necessary	122.25 F	*- FL
6	1		*FRONT R/H SIDE PANEL TOP GARNISH	Deformed	188.20 F	*188.20 FL
7	1		*FRONT R/H SIDE PANEL	Cracked	287.75 F	*287.75 FL
8	1		*FRONT R/H HEAD LAMP	Cracked	1,217.45 F	*705.00 FL
9	1		*FRONT R/H HEAD LAMP PANEL	Not Necessary	374.25 F	*- FL
10	1		*FRONT R/H HEAD LAMP LOWER RUBBER	Not Necessary	121.45 F	*- FL
11	4		*FRONT R/H HEAD LAMP LOWER RUBBER CLIP	Not Necessary	14.00 F	*- FL
12	1		*FRONT R/H DOOR	Dented	1,712.45 F	*1,455.00 FL
13	2		*FRONT R/H DOOR HINGE	Not Necessary	244.50 F	*- FL
14	1		*FRONT R/H DOOR PILLAR	Repair	631.35 F	*- FL
15	1		*FRONT R/H DOOR COMPANY STICKER	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT R/H DOOR INNER LOCK	Not Necessary	581.90 F	*- FL
17	1		*FRONT R/H DOOR INNER RUBBER	Not Necessary	374.45 F	*- FL
18	1		*FRONT R/H DOOR INNER LOWER RUBBER	Not Necessary	182.10 F	*- FL
19	1		*FRONT R/H DOOR INNER TRIM BOARD	Cracked	781.45 F	*581.00 FL
20	1		*FRONT R/H DOOR GEAR MOTOR ASSY	Not Necessary	581.10 F	*- FL
21	1		*FRONT R/H STEP PANEL	Cut	274.10 F	*274.10 FL
22	1		*FRONT R/H ARCH PANEL	Not Necessary	281.90 F	*- FL
23	1		*FRONT R/H ARCH PANEL GARNISH	Not Necessary	274.25 F	*- FL
24	1		*FRONT RH LOWER ARM	Bent	667.00 F	*667.00 FL
25	1		*FRONT RH UPPER ARM	Necessary	461.00 F	*461.00 FL
26	1		*FRONT RH KNUCKLE ARM	Damaged	654.00 F	*654.00 FL
27	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	645.00 F	*645.00 FL
28	1		*FRONT RH SHOCK ABSORBER	Bent	211.00 F	*211.00 FL
29	1		*STEERING RACK AND PINION	Bent	2,153.00 F	*2,153.00 FL
30	1		*FRONT RH WHEEL RIM	Cut	250.00 FS	*200.00 FS
31	1		*FRONT RH TYRE	Not Necessary	200.00 FS	*- FS
32	1		*FRONT RH DOOR WIRING MIRROR	Cracked	452.00 F	*452.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,726.60	10,134.50
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	2,476.13

Total Parts (\$)	15,726.60	7,658.37
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	100.00	30.00
2	TUFF KOTE	New	150.00	50.00
3	PANEL BEATING	New	1,400.00	600.00
4	SPRAY PAINTING	New	1,400.00	600.00
5	TO REMOVE & REFIT FRONT L/H DOOR ,GEAR MOTOR ,GLASS,LOCK RUBBER & TRIM BOARD	New	180.00	80.00
6	TO REMOVE FRONT UNDERCARRIAGE	New	380.00	300.00
7	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			3,760.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >