

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000587/EVD3E2  
**Date:** 05/02/2021

### REFERENCE

Insured/Claimant: LILY WIRAWAN THE Policy No: 1900108966  
Date of Loss: 12/01/2021 Nature of Claim: OD Claim No: 3993313397SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFL5639R**  
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AR9007  
Reg. Date: 10/07/2019 (Man. Year: 2019) Chassis No: GF7W0601259  
Colour: Grey Odometer: 16540 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$100,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Toyo 4 mm Rear Left Side: Toyo 4 mm  
Front Right Side: Toyo 4 mm Rear Right Side: Toyo 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,418.47	4,452.12	966.35	17.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,835.00	1,905.00	50.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,158.47</b>	<b>6,287.12</b>	<b>2,871.35</b>	<b>31.35</b>
<b>- Excess (S\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,858.47</b>	<b>5,987.12</b>	<b>2,871.35</b>	<b>32.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>620.09</b>	<b>419.10</b>	<b>200.99</b>	<b>32.41</b>
<b>Nett Amount (S\$)</b>	<b>9,478.56</b>	<b>6,406.22</b>	<b>3,072.34</b>	<b>32.41</b>

### INSPECTION

Date of Assignment: 13/01/2021  
Date Inspected: 12/01/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339  
Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*HEADLAMP ASSY, LH	Cut	1,938.00 FL	*1,938.00 FL
3	1		*LAMP ASSY, FOG, FR LH	Not Necessary	348.00 FL	*- FL
4	1		*FENDER, FR LH	Dented	688.00 FL	*688.00 FL
5	1		*MOULDING, FR WHEEL ARCH, LH	Cut	160.00 FL	*160.00 FL
6	1		*MOULDING, FR BUMPER, LH	Cut	116.00 FL	*116.00 FL
7	1		*WHEEL, DISC LHF	Cut	974.00 FL	*974.00 FL
8	1		*FACE, FR BUMPER	Broken	859.00 FL	*859.00 FL
9	1		*EXTENSION, FR BUMPER	Broken	515.00 FL	*515.00 FL
10	1		*GARNISH, FR BUMPER, LH	Cut	48.00 FL	*48.00 FL
11	1		*COVER, FR BUMPER	Not Necessary	359.00 FL	*- FL
12	1		*BRACKET, FR BUMPER SIDE, LH	Broken	18.00 FL	*18.00 FL
13	1		*GARNISH, FR BUMPER SIDE	Cut	48.00 FL	*48.00 FL
14	1		*GARNISH, FR BUMPER SIDE	Cracked	220.00 FL	*220.00 FL
15	1		*GARNISH, FR BUMPER SIDE	Broken	112.00 FL	*112.00 FL
16	1		*GRILLE ASSY, RADIATOR	Not Necessary	548.00 FL	*- FL
17	6		*RIVET,FR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL
18	10		*CLIP, RR BUMPER (Supplementary)	Necessary	30.00 FL	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,031.00</b>	<b>5,776.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (S\$)</b>	1,612.53	1,323.88
<b>Total Parts (S\$)</b>	<b>5,418.47</b>	<b>4,452.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER & LHF FENDER. REPAIR BONNET & LHF DOOR	New	1,800.00	675.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER & LHF DOOR	New	1,400.00	700.00
3	TO RENEW LHS SPORT RIM & TRANSFER TYRE	New	30.00	30.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
7	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	0.00
8	APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS	New	160.00	160.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,835.00</b>
			<b>3,740.00</b>	<b>1,835.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >