

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000592/EQD3E2

**Date:** 16/07/2021

### REFERENCE

Insured/Claimant: KHOO SENG TAT Policy No: 1800025612-01  
Date of Loss: 12/01/2021 Nature of Claim: OD Claim No: 4195096656SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX1885M**  
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGHH692349  
Reg. Date: 20/03/2018 (Man. Year: 2017) Chassis No: KNAFJ411MJ5762074  
Colour: Blue Odometer: 59704 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: S\$62,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18  
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm  
Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,735.60	2,399.20	336.40	12.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	2,280.00	800.00	25.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,815.60</b>	<b>4,679.20</b>	<b>1,136.40</b>	<b>19.54</b>
<b>+ GST 7.00/7.00% (S\$)</b>	407.09	327.54	79.55	19.54
<b>Nett Amount (S\$)</b>	<b>6,222.69</b>	<b>5,006.74</b>	<b>1,215.95</b>	<b>19.54</b>

### INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 12/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,542.00 FL	*1,542.00 FL
3	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,361.00 FL	*1,361.00 FL
4	1		*BLACK TAPE-FR DR RR, RH	Necessary	12.00 FL	*12.00 FL
5	1		*TAPE-RR DR FRAME BLACK RR, RH	Necessary	8.00 FL	*8.00 FL
6	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	58.00 FL	*- FL
7	1		*W/STRIP ASSY-FR DR SIDE RH	Not Necessary	122.00 FL	*- FL
8	1		*W/STRIP ASSY-RR DR BELT O/S RH	Not Necessary	89.00 FL	*- FL
9	1		*W/STRIP ASSY-RR DR SIDE RH	Not Necessary	114.00 FL	*- FL
10	1		*BLACK TAPE-FR DR FRAME UPR, RH (Supplementary)	Necessary	13.00 FL	*13.00 FL
11	1		*BLACK TAPE-RR DR FRAME UPR, RH (Supplementary)	Necessary	11.00 FL	*11.00 FL
12	1		*FILM-ANTI CHIPPG RH (Supplementary)	Necessary	27.00 FL	*27.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,407.00</b>	<b>2,994.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	671.40	594.80
<b>Total Parts (\$)</b>	<b>2,735.60</b>	<b>2,399.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT RH DOOR, REAR RH DOOR & AFFECTED AREA. REPAIR ON RH ROCKER PANEL	New	1,600.00	800.00
2	PAINT WORK ON FRT RH DOOR, REAR RH DOOR & RH ROCKER PANEL	New	1,050.00	1,050.00
3	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	120.00
4	TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	120.00
5	PERFORM RUST PREVENTION	New	40.00	40.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,080.00</b>
				<b>2,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >