

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21000594/Gvf3e2	
	8 SHENTON WAY TOWERSINGAPOR			Date:	25/01/2021	
	ATTN : CHAN KIAN	N CHUAN		Code:	ASM	
1.	I. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 6970U	Veh. Inspected	k	GBJ 4009Z	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M030DD	Excess (\$)		0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date		13/01/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 1.6	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	VM20133773	Colour		BLACK	
	Odometer	22692 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	165/80 R14	TOYO		6 mm	
	L/H Front Tyre	165/80 R14	TOYO		6 mm	
	R/H Rear Tyre	165/80 R14	TOYO		6 mm	
	L/H Rear Tyre	165/80 R14	TOYO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	06/01/2021	Inspect Date /	Time	13/01/2021 (05:30 PM)	
	Survey held at	GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					

Report Ref No. CS3/ASM21000594/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor