

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21000597/UTD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: MSD/VMT/20-408768-CA	
Claimant Vehicle No : GBE1303U	Insured Vehicle No : FBJ3937B	
Date of Loss: 05/12/2020	Nature of Claim: TP	Claim No: MSC/V/20-000869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE1303U		
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No: 1KD2484518	
Reg. Date: 04/09/2015 (Man. Year: 2014)	Chassis No: JTFHT02P000159371	
Colour: White	Odometer: 282553 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15	Rear Tyre Size: 195 R15
Front Left Side: Austone 6 mm	Rear Left Side: Austone 6 mm
Front Right Side: Austone 6 mm	Rear Right Side: Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,355.60	1,091.32	2,264.28	67.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	800.00	900.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,055.60	1,891.32	3,164.28	62.59
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	5,055.60	1,500.00	3,555.60	70.33

INSPECTION

Date of Assignment: 13/01/2021		
Date Inspected: 13/01/2021	Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair: 3.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE1303U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH SLIDING DOOR	Dented / Bent	1,682.40 F	*1,455.10 FL
2	1		*REAR LH FENDER (BODY PANEL)	Repair	1,308.10 F	*- FL
3	1		*REAR LH TAIL LAMP	Not Necessary	365.10 F	*- FL
					Sub Total (S\$)	3,355.60 1,455.10
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00 363.78
					Total Parts (S\$)	3,355.60 1,091.32

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
2	TO REMOVE ,REPLACE AND TRANSFER SLIDING DOOR PANEL,FITTINGS AND MECHANISMS	New	100.00	50.00
3	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PATS ETCS	New	900.00	300.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	400.00
5	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
Gross Labour Cost (\$\$)			1,700.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >