

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 19 Jan 2021

Preliminary Advice

Insured Vehicle No : FBJ3937B

TP Vehicle No : GBE1303U

Make : TOYOTA HIACE

Date of Inspection : 13/01/2021

Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT
SINGAPORE 417883

Accident Date : 05/12/2020

Assignment Date : 13/01/2021

Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,055.60
Revised Amount	:S\$	1,891.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,891.32

Lump Sum Repair	:S\$	1,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (x) Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.