



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 8324Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	BUCKLED / CRACKED	541.20	541.20
1	FRONT BUMPER RETAINER/RH	SERVICEABLE	142.80	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	361.00	-
1	FRONT BUMPER FOG LAMP COVER/RH	SERVICEABLE	112.00	-
1	FRONT HEADLAMP ASSY/RH	MTG CRACKED	745.00	745.00
	LESS 20% DISCOUNT		-380.40	-
	LESS 25% DISCOUNT		-	-321.55
			1,521.60	964.65
	<b><u>LABOUR</u></b>			
	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION.		55.00	20.00
	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.	NOT NECESSARY	120.00	-
	TO REPAIR,PANEL BEAT ON FRT AFFECTED PANEL,ALIGN ON FRT BUMPER & LABOUR TO REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	200.00
	TO PUTTY,PRIMER & SPRAY PAINT ON FRT AFFECTED PANEL,FRT BUMPER & TOUCH UP ON AFFECTED RIGHT FRT DOOR USING 2K PAINT.		600.00	200.00
			1,275.00	420.00
	<b>GRAND TOTAL</b>		<b>2,796.60</b>	<b>1,384.65</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>

Report Ref No. CS/AGI21000606/Ktf3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.