

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000607/APA3Q2
Date: 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900111264
Claimant Vehicle No :	SLJ8600X	Insured Vehicle No :	SMM1886G
Date of Loss:	07/01/2021	Nature of Claim:	TP
		Claim No:	2733039429SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8600X		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4408127
Reg. Date:	29/12/2016 (Man. Year: 2016)	Chassis No:	RU11208129
Colour:	Black	Odometer:	86596 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,821.56	5,416.32	4,405.24	44.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	2,310.00	2,270.00	49.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,401.56	7,726.32	6,675.24	46.35
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	14,401.56	6,000.00	8,401.56	58.34
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		6,400.00		

INSPECTION

Date of Assignment: 08/01/2021

Date Inspected: 08/01/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Advance Auto Garage
 10 KAKI BUKIT ROAD 2
 #03-01 FIRST EAST CENTRE
 SINGAPORE 417868

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	880.00 FL	*880.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	47.00 FL	*47.00 FL
3	2		*REAR BUMPER REFLECTOR	Cracked	282.20 FL	*282.20 FL
4	1		*REAR SIDE BUMPER	N/S Deformed	390.00 FL	*195.00 FL
5	1		*REAR END PANEL	Dented	585.00 FL	*585.00 FL
6	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 FL	*98.40 FL
7	1		*TAILLAMP	N/S Cracked	949.20 FL	*474.60 FL
8	1		*TAILGATE	Distorted	1,100.00 FL	*1,100.00 FL
9	1		*TAILGATE LOCK	Jammed	182.50 FL	*182.50 FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	128.00 FL	*128.00 FL
11	2		*TAILGATE LAMP	Not Necessary	826.40 FL	*- FL
12	2		*TAILGATE LAMP RUBBER GASKET	Not Necessary	77.00 FL	*- FL
13	2		*TAILGATE DAMPER	Not Necessary	365.40 FL	*- FL
14	1		*TAILGATE OUTER GARNISH	Not Necessary	325.00 FL	*- FL
15	1		*TAILGATE INNER TRIM BOARD	Cracked	285.60 FL	*285.60 FL
16	1		*TAILGATE BUZZER SENSOR	Cracked	85.20 FL	*85.20 FL
17	1		*TAILGATE ANTENNA SENSOR	Not Necessary	60.10 FL	*- FL
18	1		*TAILGATE GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
19	1		*HONDA LOGO	Not Necessary	30.40 FL	*- FL
20	1		*VEZEL EMBLEM	Necessary	45.90 FL	*45.90 FL
21	1		*SPARE TYRE PANEL	Repair	1,130.00 FL	*- FL
22	1		*SPARE TYRE PANEL TOP COVER	Deformed	306.60 FL	*306.60 FL
23	1		*SPARE TYRE PANEL TOOLS TRAY SPONGE	Cracked	285.40 FL	*285.40 FL
24	1		*SPARE TYRE PANEL UNDERCOVER	Deformed	225.10 FL	*225.10 FL
25	1		*REAR FENDER ARC GARNISH	N/S Cracked	392.00 FL	*196.00 FL
26	2		*REAR FENDER INNER SHIELD	Not Necessary	295.00 FL	*- FL
27	2		*REAR FENDER INNER TRIM BOARD	Deformed	610.40 FL	*610.40 FL
28	1		*REAR EXHAUST PIPE	Not Necessary	598.60 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	28.50 FL	*- FL
30	1		*REAR EXHAUST GASKET	Not Necessary	48.30 FL	*- FL
31	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
32	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
33	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
35	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
37	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	25.00 FS	*- FS
38	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
39	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
40	1		*SET SPARE TYRE PANEL UNDERCOVER CLIPS	Necessary	30.00 FS	*30.00 FS
41	2		*SET REAR FENDER ARC GARNISH CLIPS	Necessary	60.00 FS	*20.00 FS
42	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
43	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
					Sub Total (\$)	11,978.20
					- List Item Discount on L Items 20.00/20.00% (\$)	2,156.64
					Total Parts (\$)	9,821.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,600.00	900.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	900.00
3	WIRING CHECK	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE REAR CAMERA	New	100.00	60.00
6	TO REMOVE UPHOLSTERY AND REAR SEAT	New	350.00	80.00
7	TO SPRAY TUFF COAT	New	150.00	80.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
11	TOWING FEES	New	100.00	0.00
Gross Labour Cost (S\$)			4,580.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >