

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000616/EGS3Q2

Date: 05/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423436

Claimant
Vehicle No : SLV7040E **Insured Vehicle No :** SKU6207R

Date of Loss: 12/01/2021 Nature of Claim: TP Claim No: 1017793070SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7040E		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGHH689042
Reg. Date:	11/01/2018 (Man. Year: 2017)	Chassis No:	KNAFJ411MJ5757633
Colour:	Blue	Odometer:	23837 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,549.80	4,358.40	4,191.40	49.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	3,730.00	1,400.00	27.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,679.80	8,088.40	5,591.40	40.87
+ GST 7.00/7.00% (S\$)	957.59	566.19	391.40	40.87
Nett Amount (S\$)	14,637.39	8,654.59	5,982.80	40.87
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,726.59		

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 13/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -FR BUMPER	Broken	633.00 FS	*506.40 FS
3	1		*GRILLE ASSY -RADIATOR	Not Necessary	160.00 FS	*- FS
4	1		*DUCT ASSY -AIR CURTAIN ,LH	Crushed	6.00 FS	*4.80 FS
5	1		*MOULDING -FRONT BUMPER A/INTAKE	Not Necessary	91.00 FS	*- FS
6	1		*COVER -BLANKING FR FOG LH	Not Necessary	18.00 FS	*- FS
7	1		*AIR DUCT -FR BUMPE ,LH	Crushed	33.00 FS	*26.40 FS
8	1		*BRACKET -FR BUMPER SIDE MTG ,LH	Broken	13.00 FS	*10.40 FS
9	1		*LAMP ASSY -HEAD,LH	Broken	810.00 FS	*648.00 FS
10	1		*GUARD ASSY -FRONT WHEEL ,LH	Torn	95.00 FS	*76.00 FS
11	1		*CARRIER ASSY -FRONT END MODULE	Broken	675.00 FS	*540.00 FS
12	1		*PANEL -FENDER ,LH	Dented	376.00 FS	*300.80 FS
13	1		*INSULATOR -FENDER LH	Not Necessary	28.00 FS	*- FS
14	1		*PANEL ASSY -FRONT DOOR ,LH	Not Necessary	1,542.00 FS	*- FS
15	1		*BLACK TAPE-FRT DOOR FRAME UPR	Not Necessary	13.00 FS	*- FS
16	1		*BLACK TAPE-FR DR RR ,LH	Not Necessary	12.00 FS	*- FS
17	1		*DUCT ASSY -EXTENSION	Broken	144.00 FS	*115.20 FS
18	1		*HUB ASSY -FR WHEEL	Not Necessary	150.00 FS	*- FS
19	1		*KNUCKLE -FRONT AXLE ,LH	Not Necessary	350.00 FS	*- FS
20	1		*GEAR ASSY -STEERING	Not Necessary	832.00 FS	*- FS
21	1		*STRUT ASSY -FR LH	Bent	313.00 FS	*250.40 FS
22	1		*BEARING -STRUT	Necessary	54.00 FS	*43.20 FS
23	1		*STAY LH	Not Necessary	23.00 FS	*- FS
24	1		*ARM COMPLTE -FR LWR ,LH	Bent	380.00 FS	*304.00 FS
25	1		*CROSSMEMBER COMPL	Bent	1,330.00 FS	*1,064.00 FS
26	1		*LINK ,STABILIZER	Bent	57.60 FS	*57.60 FS
27	1		*SENSOR ASSY -ABS FRONT WHEEL ,LH	Torn	158.40 FS	*158.40 FS
28	1		*INSULATOR ASSY -STRUT	Bent	74.40 FS	*74.40 FS
29	1		*GARNISH -RADIATOR GRILLE ,UPR	Broken	43.20 FS	*43.20 FS
30	1		*ABSORBER -FRONT BUMPER ENERGY	Broken	67.20 FS	*67.20 FS
31	1		*ORNAMENT -KIA NO.115	Necessary	25.60 FS	*25.60 FS
32	10		*CLIPS	Necessary	16.00 FS	*16.00 FS
33	4		*RETAINER	Necessary	6.40 FS	*6.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,549.80** **4,358.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE FRONT SUPPORT PANEL	New	400.00	400.00
2	RENEW FRT BUMPER ,FRT FENDER LH ,FRT DOOR LH ,FRT SUPPORT PANEL	New	2,400.00	1,200.00
3	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	160.00	0.00
4	SPRAY PAINT FOR FRT BUMPER ,FRT FENDER LH ,FRT DOOR LH	New	1,050.00	1,050.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
6	TRANSFER FRT LEFT RIM	New	30.00	30.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	RENEW FRT UNDER CARRIAGE	New	400.00	400.00
10	SUPPLY FRT LEFT RIM	New	380.00	380.00
11	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	0.00
Gross Labour Cost (\$\$)			5,130.00	3,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >