



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 7878T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	446.45	446.45
1	REAR BUMPER SIDE RETAINER LH	CRACKED	181.85	145.20
1	REAR FENDER GARNISH LH	DISTORTED	371.75	151.10
1	REAR TAILLAMP LH	CRACKED	386.45	386.45
	LESS 25% DISCOUNT		-346.62	-282.30
			1,039.88	846.90
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	300.00	-
			330.00	-
	<b><u>LABOUR</u></b>			
	TO REMOVE & REFIX PARKING SENSOR ASSY AND RETIFY FOR PROPER FUNCTIONING.		80.00	40.00
	TO DIAGNOSE, REPLACE/OR REPAIR TO RETIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	100.00	-
	TO RESPRAY, PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE DAMAGED BODYPARTS, REPAIR, ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	250.00
			1,580.00	690.00
	<b>GRAND TOTAL</b>		<b>2,949.88</b>	<b>1,536.90</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,200.00</b>

Report Ref No. CS/SMO21000621/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.