



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDW 3136D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	1,150.20	-
1	REAR FENDER N/S	BADLY DENTED	1,295.20	1,295.20
1	REAR FENDER UNDER COVER N/S	NOT NECESSARY	288.30	-
1	SET REAR FENDER UNDER COVER CLIPS N/S	NECESSARY	40.00	40.00
1	REAR WINDSCREEN MOULDING	NECESSARY	115.30	115.30
1	REAR BUMPER	DEEP CUT	1,206.20	1,206.20
1	REAR BUMPER SIDE RETAINER N/S	NOT NECESSARY	62.50	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR SPORT RIM N/S	CUT / BENT	1,050.00	1,050.00
1	REAR WHEEL HUB BEARING N/S	DAMAGED	350.00	350.00
1	REAR KNUCKLE ARM N/S	BENT	482.30	482.30
1	REAR LOWER ARM N/S	SERVICEABLE	466.50	-
	LESS 20% DISCOUNT		-	-917.80
			6,556.50	3,671.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	50.00
1	REAR TYRE N/S (SN)	NOT NECESSARY	250.00	-
			350.00	100.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	100.00
	TO DISMANTLE & REFIX FUEL TANK.		100.00	60.00
	TO DISMANTLE & REFIX REAR DOOR MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.		180.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	80.00
	TO SPRAY RUST PROOFING.		80.00	30.00

Report Ref No. CS/TP21000625/Uqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPIAR OF REAR DOOR N/S. TO PUTTY & SPRAY PAINTING.		900.00	800.00
			1,280.00	900.00
			3,140.00	2,280.00
GRAND TOTAL			10,046.50	6,051.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00

Report Ref No. CS/TP21000625/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.