



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1587A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER SIDE PANEL-LH (SN)	BENT	2,110.00	2,110.00
2	TAIL LIGHT RIVETTED CAP NUT (SN)	NOT NECESSARY	4.00	-
1	REAR WINDOW (SN)	NECESSARY	742.00	741.50
2	PRIMER (SN)	NECESSARY	76.00	37.20
1	SIDE WINDOW (SN)	NECESSARY	520.00	519.50
1	OUTER LED TAIL LIGHT-LH (SN)	NOT NECESSARY	800.00	-
1	OUTER TRIM TAIL LIGHT-LH (SN)	NOT NECESSARY	27.00	-
2	GROMMET (SN)	NOT NECESSARY	64.00	-
1	WHEEL HOUSING LINER (SN)	NOT NECESSARY	223.00	-
1	WHEEL HOUSING LINER ATTACHMENT PARTS (SN)	NOT NECESSARY	81.00	-
1	GUIDE SECTION (SN)	NECESSARY	60.00	60.00
1	ACRYLIC SEALANT (SN)	NECESSARY	180.00	180.00
1	CAVITY WAX (SN)	NECESSARY	140.00	140.00
1	STOPNE CHIP (SN)	NECESSARY	180.00	180.00
1	METAL FILLER POWDER (SN)	NECESSARY	280.00	280.00
1	REAR W/S SEALANT (SN)	NECESSARY	200.00	200.00
1	1/4 GLASS SEALANT (SN)	NECESSARY	100.00	100.00
1	SUNDRIES (SN)	NECESSARY	400.00	19.40
1	AUDI EMBLEM (SN) (ADDITIONAL)	NECESSARY	113.00	112.50
1	A3 EMBLEM (SN) (ADDITIONAL)	NECESSARY	87.00	86.60
1	TFSI EMBLEM (SN) (ADDITIONAL)	NECESSARY	87.00	86.60
			6,474.00	4,853.30
	<u>LABOUR</u>			
	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION.		280.00	280.00
	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.		600.00	600.00
	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.		1,400.00	1,400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.		1,400.00	1,400.00
	TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND WELD LHS REAR FENDER.RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		5,600.00	4,900.00
	TO RESPRAY LHS REAR FENDER,LHS SILL PANEL,DOOR ENTRANCES,ROOF CHANNEL,DRAIN PANEL AND END PANELLING.TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.		3,800.00	3,100.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
	TO REPAIR AND RESPRAY REAR LID. (ADDITIONAL)		1,400.00	875.00
	TO RESPRAY REAR BUMPER. (ADDITIONAL)		900.00	700.00
			15,572.00	13,447.00
GRAND TOTAL			22,046.00	18,300.30
RECOMMENDED COST OF REPAIRS				18,300.30

Report Ref No. CS1/LPC21000626/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.