# Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

## Estimated Labour Charges for Accident Vehicle. SLA 1587 U

5/n	Nature of Jobs		Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N	\$ 280.00
2	To renew rear windscreen and lhs 1/4 glass to facillitate fender renewal.	5/N	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$ 1,400.00
5	To dismantle rear bumper and rear lid. Cut out and weld lhs rear fender. Re-organize rear crash management components. Reinstall all parts removed.	Y	\$ 5,600.00 4
6	To respray lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$ 3,800.00 3,7
7	To carry out diagnostic check.	S/N	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 13,272.00

## **Premium Automobiles**

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

### Material List for Accident Vehicle Regn No. SLA 1587 U

				Damaged Part	s & Prices
S/N	Parts Description		_	S/Nett	Remark
1	REAR FENDER SIDE PANEL - LH		\$	2,110.00	
2	TAIL LIGHT RIVETTED CAP NUT	2	\$	4.00	
3	REAR WINDOW Voc.		\$	742.00	
4	PREMIER ?	2	\$	76.00	
5	SIDE WINDOW VALLE		\$	520.00	
6	OUTER LED TAIL LGHT - LH ?		\$	800.00	
7	OUTER TRIM TAIL LIGHT - LH ?		\$	27.00	
8	GROMMET ?	2	\$	64.00	
9	WHEEL HOUSING LINER ?		\$	223.00	
10	WHEEL HOUSING LINNER ATTACHEMENT PARTS	7	\$	81.00	
11	GUIDE SECTION -		\$	60.00	
12	ACRYLIC SEALANT >		\$	180.00	
13	CAVITY WAX 3 ?		s	140.00	
14	STOPNE CHIP ?		\$	180.00	
15	METAL FILLER POWDER ?		\$	280.00	
16	REAR W/S SEALANT		\$	200.00	
17	1/4 GLASS SEALANT		\$	100.00	
18	SUNDRIES		\$	400.00 ?	
	TOTAL SPARE PARTS CHARGES		\$	6,187.00	
	TOTAL LABOUR CHARGES	:	\$	13,272.00	
	GRAND TOTAL	;	\$	19,459.00	
	All charges are not including of CCT				

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved Spare parts are Special Nett.

### dence and Annotations

as indicated by **Green** markings are deemed consistent and areas or parts indicated by **Red** markings are not sistent.



Photo 1 LHF VIEW



Photo 2 FRT VIEW



Photo 3 RHF VIEW



Photo 4 RHR VIEW



Photo 5 REAR VIEW



Photo 6 LHR VIEW



Photo 7 LHR FENDER BENT




Photo 8 LHR QUARTER GLASS VIEW



Photo 9 LHR QUARTER GLASS VIEW 2



Photo 10 LHR TAIL LAMP VIEW




Photo 11 LHR TAIL LAMP VIEW 2



Photo 12 ODOMETER READING



Photo 13 CHASSIS NO



Photo 14 REAR BOOTLID PANEL VIEW



Photo 15 REAR BOOTLID PANEL CUT/SCRATCHED - REPAIR



Photo 16 REAR BOOTLID PANEL CUT/SCRATCHED - REPAIR



Photo 17 BEFORE PAINT VIEW 1



Photo 18 BEFORE PAINT VIEW 2



Photo 19 BEFORE PAINT VIEW 3



Photo 20 BEFORE PAINT VIEW 4



Photo 21 BEFORE PAINT VIEW 5



Photo 22 BEFORE PAINT VIEW 6