

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000627/APA3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100445128	
Claimant Vehicle No : GBJ1025X	Insured Vehicle No : EJ8889M	
Date of Loss: 09/01/2021	Nature of Claim: TP	Claim No: 9132450348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ1025X		
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No: 1KD2837120	
Reg. Date: 02/01/2019 (Man. Year: 2018)	Chassis No: JTFAT35Y70K212272	
Colour: Silver	Odometer: 62868 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/70 R15C	Rear Tyre Size: 155 R12C	
Front Left Side: KAPSEN 6 mm	Rear Left Side: Yokohama 6 mm	
Front Right Side: KAPSEN 6 mm	Rear Right Side: Yokohama 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,792.95	3,174.92	18,618.03	85.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,090.00	2,230.00	1,860.00	45.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,882.95	5,404.92	20,478.03	79.12
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	25,882.95	4,300.00	21,582.95	83.39
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,782.00		
Global Sum Settlement (S\$)		4,780.00		

INSPECTION

Date of Assignment: 11/01/2021		
Date Inspected: 11/01/2021 Inspected At:	Cn Motors Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT Singapore 417883	
Estimated Period of Repair: 5.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,714.40 F	*1,365.00 FL
2	2		*REAR TAILGATE TOP SIDE HANDLE	Not Necessary	374.60 F	*- FL
3	1		*REAR TAILGATE LOWER SIDE LOCK	O/S Bent	342.80 F	*171.40 FL
4	4		*REAR TAILGATE LOWER SIDE HINGE	Bent (2 PCS ONLY)	726.80 F	*96.40 FL
5	1		*REAR TAILGATE LOWER SIDE STOPPER	O/S Missing	62.40 F	*31.20 FL
6	1		*REAR TAILGATE LOWER SIDE STOPPER BRACKET	O/S Bent	337.20 F	*168.60 FL
7	1		*REAR TAILGATE LOWER MEMBER	Dented	750.00 F	*545.00 FL
8	1		*REAR TAILGATE LOWER MEMBER DYNA STICKER	Necessary	35.00 F	*35.00 FL
9	1		*REAR TAIL LAMP	O/S Cut	655.00 F	*285.00 FL
10	1		*REAR TAIL LAMP PANEL	O/S Bent	748.90 F	*165.00 FL
11	2		*REAR REVERSE SENSOR	Damaged	400.00 FS	*200.00 FS
12	1		*REAR FLOOR PANEL	Repair	10,000.00 F	*- FL
13	1		*REAR NUMBER PLATE LAMP	Not Necessary	131.35 F	*- FL
14	1		*REAR NUMBER PLATE PANEL	Bent	127.30 F	*127.30 FL
15	1		*REAR SPARE TYRE LOCK	Damaged	283.00 F	*283.00 FL
16	1		*REAR EXHAUST	Bent	980.10 F	*547.00 FL
17	2		*REAR EXHAUST MOUNTING	Not Necessary	76.00 F	*- FL
18	1		*REAR CENTRE EXHAUST	Not Necessary	678.10 F	*- FL
19	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*10.00 FS
20	1		*REAR TAILGATE TOYOTA STICKER	Necessary	60.00 FS	*60.00 FS
21	1		*REAR TAILGATE 5 PAX STICKER	Necessary	30.00 FS	*10.00 FS
22	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
23	2		*REAR SPARE TYRE	Not Necessary	700.00 FS	*- FS
24	1		*REAR FLOOR PANEL ALUMINIUM COVER	Not Necessary	1,500.00 FS	*- FS
25	1		*REAR TAIL GATE ALUMINIUM COVER	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,792.95	4,129.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	954.98
Total Parts (\$\$)	21,792.95	3,174.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT TAILGATE ALUMINIUM COVER	New	380.00	60.00
2	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
3	TO CHECK WIRING	New	80.00	30.00
4	TOWING FEE	New	100.00	0.00
5	TUFF KOTE	New	150.00	60.00
6	PANEL BEATING	New	1,600.00	1,000.00
7	SPRAY PAINTING	New	1,400.00	1,000.00
Gross Labour Cost (\$\$)			4,090.00	2,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >