

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21000628/KVF3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLW8458Y

Insured Vehicle No : XD6782G

Date of Loss: 13/01/2021

Nature of Claim: TP

Claim No: CDMCG21000072

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW8458Y**

Make & Model: HONDA CIVIC, 1.3 EC8 (M)

Engine No: L15B71672748

Reg. Date: 05/03/2018 (Man. Year: 2017)

Chassis No: MRHFK4840HT000031

Colour: Metallic Pearl White

Odometer: 37053 km

Engine Capacity: 1498 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R18

Rear Tyre Size: 235/40R18

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,452.60	1,298.40	4,154.20	76.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,135.00	1,505.00	57.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,092.60	2,433.40	5,659.20	69.93
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	8,092.60	1,950.00	6,142.60	75.90
+ GST 7.00/7.00% (S\$)	566.48	136.50	429.98	75.90
Nett Amount (S\$)	8,659.08	2,086.50	6,572.58	75.90

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 17/02/2021 Inspected At:

Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2021)
Parts:	144	HONDA CIVIC 1.3 EC8 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW8458Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR QUARTER PANEL RHS	Bent	955.40 FL	*846.60 FL
2	1		*REAR FENDER INNER SHIELD RHS	Serviceable	225.20 FL	*- FL
3	1		*REAR BUMPER	Mtg Cracked	866.40 FL	*681.40 FL
4	1		*REAR BUMPER RETAINER RHS	Distorted	32.50 FL	*32.50 FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	488.50 FL	*- FL
6	1		*REAR END PANEL	Repair	625.50 FL	*- FL
7	1		*TAILLAMP ASSY RHS	Serviceable	723.50 FL	*- FL
8	1		*REAR LOWER ARM RHS	Serviceable	405.00 FL	*- FL
9	1		*REAR SHOCK ABSORBER SET RHS	Serviceable	750.00 FL	*- FL
10	1		*REAR WHEEL KNUCKLE RHS	Serviceable	625.00 FL	*- FL
11	1		*REAR WHEEL BEARING & HUB RHS	Serviceable	518.75 FL	*- FL
12	1		*SET REAR RHS FENDER CLIPS	Not Necessary	50.00 FS	*- FS
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
14	1		*SET REVERSE SENSOR	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,695.75	1,610.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,243.15	312.10
Total Parts (\$\$)	5,452.60	1,298.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	1,000.00	440.00
3	TO REMOVE AND REFIT REAR BUMPER BODYKIT	New	300.00	0.00
4	TO REMOVE AND REFIT REAR TYRE RHS (FOR REPLACE QUARTER PANEL)	New	100.00	0.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
6	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	15.00
7	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	30.00
Gross Labour Cost (\$\$)			2,640.00	1,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >