



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101577

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 12/03/2021
Reference CC6/FCI21000629/Aea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLL 9225D

Insured Veh. SH 3388U

Claim No.

Policy No.

Accident Date 08/01/2021

Inspection Date 11/01/2021

Description	Total
Survey Inspection	448.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	448.00
GST (7%)	31.36
Grand Total	479.36

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI21000629/Aea3q2	
			Date: 12/03/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 3388U	Veh. Inspected	SLL 9225D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMGK5850HX201172	Colour	BLUE	
Odometer	45819 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	DUNLOP	6 mm	
L/H Front Tyre	185/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2021	Inspection Date	11/01/2021	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9225D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	545.20	545.20
2	REAR BUMPER SIDE HOLDER @\$24.20	NECESSARY	48.40	48.40
2	REAR BUMPER SIDE GRILLE	NOT NECESSARY	138.00	-
1	REAR END PANEL	DENTED	355.00	355.00
1	REAR END PANEL TOP GARNISH	DEFORMED	121.60	121.60
1	REAR END PANEL ANTENNA SENSOR	CRACKED	118.90	118.90
1	REAR END PANEL BUZZER	CRACKED	85.60	85.60
2	TAILLAMP @\$282.00	CRUSHED	564.00	564.00
2	TAILLAMP PANEL @\$176.20	O/S DENTED	352.40	176.20
1	TAILGATE	DISTORTED	845.90	845.90
1	TAILGATE LOCK	DAMAGED	161.80	161.80
1	TAILGATE WEATHERSTRIPE	CRUSHED	138.50	138.50
1	TAILGATE INNER TRIM BOARD	CRACKED	285.90	285.90
1	TAILGATE INNER HOLDER	DEFORMED	34.20	34.20
2	TAILGATE LAMP @\$193.50	O/S CUT	387.00	193.50
1	TAILGATE OUTER CHROME GARNISH	NOT NECESSARY	286.90	-
1	TAILGATE GLASS MOULDING	NECESSARY	95.40	95.40
2	REAR FENDER INNER TRIM BOARD @\$258.40	O/S CRACKED	516.80	258.40
1	SPARE TYRE PANEL	DISTORTED	897.30	897.30
1	SPARE TYRE PANEL TOP BOARD	DEFORMED	287.60	287.60
1	SPARE TYRE PANEL TOOLS SPONGE TRAY	CRACKED	262.40	262.40
1	REAR EXHAUST PIPE	BENT	552.80	552.80
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	35.00	-
1	REAR EXHAUST HEAT SHIELD	CRUMPLED	65.90	65.90
1	HONDA LOGO	NOT NECESSARY	35.40	-
1	JAZZ WORDING	NECESSARY	40.40	40.40
	LESS 20% DISCOUNT		-1,451.66	-1,226.98
			5,806.64	4,907.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	30.00	30.00

Report Ref No. CC6/FCI21000629/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR CAMERA (SN)	NOT NECESSARY	480.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	SET TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
2	SETS REAR FENDER INNER TRIM BOARD CLIPS @\$30.00 (SN)	NECESSARY	60.00	30.00
			1,120.00	490.00
	LABOUR			
	PANEL BEATING,REMOVE AND REFIT PARTS.		1,600.00	1,300.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	1,200.00
	WIRING CHECK.		50.00	30.00
	TO APPLY TUFF-COAT.		180.00	120.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY AND REAR SEAT.		350.00	250.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO REMOVE TAILGATE GLASS.		180.00	120.00
	TO REMOVE EXHAUST PIPE.		150.00	80.00
	TOWING FEES.	NOT NECESSARY	60.00	-
	TO REMOVE REAR VIDEO RECORDER.		100.00	50.00
			4,420.00	3,330.00
GRAND TOTAL			11,346.64	8,727.92

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,800.00
---	--	--	-----------------

Report Ref No. CC6/FCI21000629/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 9225D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 9225D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 9225D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

