

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000632/KTD3E2

**Date:** 03/02/2021

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Policy No: 999995580

Date of Loss: 09/01/2021

Nature of Claim: OD

Claim No: 3069111477SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU7123S**  
Make & Model: MERCEDES-BENZ CLA180, 1.6 Coupe (C117) Facelift (A) Engine No: 27091030696345  
Reg. Date: 13/08/2015 (Man. Year: 2015) Chassis No: WDD1173422N233382  
Colour: Metallic Purple Odometer: 126054 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: S\$77,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18  
Front Left Side: Goodyear 8 mm Rear Left Side: Goodyear 8 mm  
Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                               | 3,864.85        | 1,784.10        | 2,080.75        | 53.84        |
| Miscellaneous Items                 | 0.00            | 0.00            | 0.00            |              |
| Labour                              | 2,130.00        | 475.00          | 1,655.00        | 77.70        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00            |              |
| Towing                              | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>5,994.85</b> | <b>2,259.10</b> | <b>3,735.75</b> | <b>62.32</b> |
| <b>- Excess (S\$)</b>               | <b>1,200.00</b> | <b>1,200.00</b> | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>4,794.85</b> | <b>1,059.10</b> | <b>3,735.75</b> | <b>77.91</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>335.64</b>   | <b>74.14</b>    | <b>261.50</b>   | <b>77.91</b> |
| <b>Nett Amount (S\$)</b>            | <b>5,130.49</b> | <b>1,133.24</b> | <b>3,997.25</b> | <b>77.91</b> |

### INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 14/01/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                                       | Condition   | Repairer's | Amount    |
|-----|-----|----------|---|-------------|------------|-----------|
| 1   | 1   |          | *HEADLAMP ASSY-RH (WCP)                           | Serviceable | 1,650.00 F | *- F      |
| 2   | 1   |          | *FRONT BUMPER (WCP)                               | Torn        | 880.00 F   | *880.00 F |
| 3   | 1   |          | *FRONT BUMPER SIDE RETAINER-RH (WCP)              | Cracked     | 38.00 F    | *38.00 F  |
| 4   | 1   |          | *FRONT BUMPER BASIC MOUNTING (WCP)                | Cracked     | 165.00 F   | *165.00 F |
| 5   | 1   |          | *FRONT BUMPER INSIDE PARTS-RH (WCP)               | Serviceable | 120.00 F   | *- F      |
| 6   | 1   |          | *FRONT BUMPER UNDER COVER (WCP)                   | Torn        | 265.00 F   | *265.00 F |
| 7   | 6   |          | *FRONT BUMPER SENSORS (WCP)                       | Necessary   | 48.00 F    | *48.00 F  |
| 8   | 1   |          | *FRONT BUMPER CLIPS (WCP)<br>(15PCS)              | Necessary   | 90.75 FS   | *50.00 FS |
| 9   | 1   |          | *FRONT FENDER INNER SHIELD-RH (WCP)               | Cracked     | 135.00 F   | *135.00 F |
| 10  | 1   |          | *FRONT FENDER INNER SHIELD CLIPS (WCP)<br>(20PCS) | Necessary   | 143.00 FS  | *50.00 FS |

F=Franchise part. S=SpcNett.

|   |          |          |
|---|----------|----------|
| Sub Total (\$)                          | 3,534.75 | 1,631.00 |
| + Margin on L,N Items 10.00/10.00% (\$) | 330.10   | 153.10   |
| Total Parts (\$)                        | 3,864.85 | 1,784.10 |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount        |
|---------------------------------|---|----------|-----------------|---------------|
| <b>Labour Items</b>             |   |          |                 |               |
| 1                               | TO PANEL BEAT AND STRAIGHTEN RH FRONT FENDER,RH CHASSIS FRAME,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME | New      | 800.00          | 200.00        |
| 2                               | TO REMOVE AND REFIT FRONT BUMPER SENSOR   | New      | 100.00          | 60.00         |
| 3                               | TO CHECK AND RECTIFY WIRING SYSTEM  | New      | 80.00           | 15.00         |
| 4                               | TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS  | New      | 800.00          | 200.00        |
| 5                               | TO RESET AND REPROGRAME HEADLAMP FAULT CODE   | New      | 350.00          | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>2,130.00</b> | <b>475.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >