

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/196-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI21000638/Kqd3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	01/02/2021	
			Co	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFM 8898J	Veh. Inspected		SMJ 8985Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008684/CH	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		13/01/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GP72004132	Colour		METALLIC GREY	
	Odometer	101341 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	TOURADOR		7 mm	
	L/H Front Tyre	185/60 R15	TOURADOR		7 mm	
	R/H Rear Tyre	185/60 R15	TOURADOR		7 mm	
	L/H Rear Tyre	185/60 R15	TOURADOR		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/01/2021	Inspection Date		18/01/2021	
	Survey held at	Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2				
	Repairer	MASSIVE TRADING & AUTO				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: