



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM21000639/Kga3q2 Date: 15/04/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 7791D	Veh. Inspected	SDZ 9222H	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M034PA	Excess (\$)	0.00	
Assign From		Assign Date	13/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ATH208046893	Colour	METALLIC PEARL WHITE	
Odometer	201363 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	GITI	8 mm	
L/H Front Tyre	245/45 R18	GITI	8 mm	
R/H Rear Tyre	245/45 R18	GITI	8 mm	
L/H Rear Tyre	245/45 R18	GITI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/01/2021	Inspection Date	13/01/2021	
Survey held at	AT AUTO CONSULTANT 113 TECK WHYE LANE #05-650 SINGAPORE 680113			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	