

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21000640/EVF3Q2**Date:** 09/03/2021**REFERENCE**

Insured/Claimant: ANG TECK LIP Policy No: 1900117630
Date of Loss: 12/01/2021 Nature of Claim: OD Claim No: 6117161630SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN3878L**
Make & Model: KIA STONIC, 998cc (A) Engine No: G3LCKP067466
Reg. Date: 06/08/2019 (Man. Year: 2019) Chassis No: KNAD6811VL6319558
Colour: Yellow Odometer: 13327 km
Engine Capacity: 998 cc
Market Value/New Car Price: S\$77,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R17 Rear Tyre Size: 205/55R17
Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm
Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,110.00	9,992.80	4,117.20	29.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,930.00	8,650.00	6,280.00	42.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,040.00	18,642.80	10,397.20	35.80
+ GST 7.00/7.00% (S\$)	2,032.80	1,305.00	727.80	35.80
Nett Amount (S\$)	31,072.80	19,947.80	11,125.00	35.80

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 14/01/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 19.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-RR BUMPER LWR	Crushed	366.00 FL	*366.00 FL
2	1		*CAP-RR HOOK	Not Necessary	5.00 FL	*- FL
3	1		*SKID PLATE-RR BUMPER	Crushed	122.00 FL	*122.00 FL
4	1		*COVER-RR BUMPER SIDE UNDER	Not Necessary	62.00 FL	*- FL
5	1		*MOULDING ASSY-RR BUMPER SIDE,L	Broken	152.00 FL	*152.00 FL
6	1		*MOULDING ASSY-RR BUMPER SIDE,R	Broken	152.00 FL	*152.00 FL
7	1		*LAMP ASSY-REAR FOR & R/REFL,LH	Not Necessary	111.00 FL	*- FL
8	1		*LAMP ASSY-REAR FOR & R/REFL,RH	Not Necessary	111.00 FL	*- FL
9	1		*WIRING HARNESS-BWS EXT	Not Necessary	245.00 FL	*- FL
10	1		*BEAM-RR BUMPER	Broken	419.00 FL	*419.00 FL
11	1		*BRACKET-RR BEAM LWR MTG,LH	Not Necessary	7.00 FL	*- FL
12	1		*BRACKET-RR BEAM LWR MTG,RH	Not Necessary	5.00 FL	*- FL
13	1		*BRACKET-RR BEAM UPR MTG	Not Necessary	7.00 FL	*- FL
14	1		*STAY-RR BUMPER LH	Bent	55.00 FL	*55.00 FL
15	1		*STAY-RR BUMPER RH	Bent	55.00 FL	*55.00 FL
16	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	32.00 FL	*- FL
17	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Broken	27.00 FL	*27.00 FL
18	1		*BRACKET ASSY-RR BUMPER SIDE,RH	Broken	27.00 FL	*27.00 FL
19	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	378.00 FL	*- FL
20	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	378.00 FL	*- FL
21	1		*PANEL ASSY-TAIL GATE	Dented	1,010.00 FL	*1,010.00 FL
22	1		*HINGE ASSY-TAIL GATE	Not Necessary	28.00 FL	*- FL
23	1		*GLASS ASSY-TAIL GATE	Broken	395.00 FL	*395.00 FL
24	1		*GARNISH-T/GATE UPR,LH	Not Necessary	66.00 FL	*- FL
25	1		*GARNISH-T/GATE UPR,RH	Not Necessary	66.00 FL	*- FL
26	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL
27	1		*EMBLEM-STONIC	Necessary	26.00 FL	*26.00 FL
28	1		*EMBLEM-TURBO G.D.I	Necessary	38.00 FL	*38.00 FL
29	1		*PANEL ASSY-TAIL GATE TRIM	Cut	153.00 FL	*153.00 FL
30	1		*W/STRIP TAIL GATE OPNG	Not Necessary	91.00 FL	*- FL
31	1		*STRIKER ASSY-T/GATE	Not Necessary	31.00 FL	*- FL
32	1		*LATCH ASSY-TAIL GATE	Not Necessary	106.00 FL	*- FL
33	1		*LIFTER ASSY-TAIL GATE,LH	Not Necessary	94.00 FL	*- FL
34	1		*LIFTER ASSY-TAIL GATE,RH	Not Necessary	94.00 FL	*- FL
35	1		*PANEL ASSY-REAR FLOOR,RR	Dented	204.00 FL	*204.00 FL
36	1		*PANEL ASSY-BACK	Dented	345.00 FL	*345.00 FL
37	1		*TRIM ASSY-COVERING SHELF	Broken	198.00 FL	*198.00 FL
38	1		*TRIM ASSY-RR TRANSVERSE	Broken	55.00 FL	*55.00 FL
39	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	327.00 FL	*- FL
40	2		*LAMP ASSY-LICENSE PLATE	Broken	238.00 FL	*238.00 FL
41	1		*LAMP ASSY-REAR COMB INSIDE,LH	Cut	608.00 FL	*608.00 FL
42	1		*LAMP ASSY-REAR COMB INSIDE,RH	Broken	608.00 FL	*608.00 FL
43	1		*LAMP ASSY-REAR COMB OUTSIDE,LH	Broken	654.00 FL	*654.00 FL
44	1		*LAMP ASSY-REAR COMB OUTSIDE,RH	Cut	654.00 FL	*654.00 FL
45	1		*MUFFLER ASSY-REAR	Not Necessary	665.00 FL	*- FL
46	1		*PROTECTOR-HEAT REAR	Bent	49.00 FL	*49.00 FL
47	1		*GASKET-EXHAUST PIPE	Not Necessary	14.00 FL	*- FL
48	1		*MUFFLER ASSY-CENTER	Not Necessary	362.00 FL	*- FL
49	1		*MOTOR & LINKAGE ASSY-REAR WPR	Not Necessary	241.00 FL	*- FL
50	1		*BLADE ASSY-WIPER,RR	Cut	39.00 FL	*39.00 FL
51	1		*ARM & HEAD CAP ASSY-RR WIPER	Cut	47.00 FL	*47.00 FL
52	1		*GARNISH ASSY-RR DE SIDE LH	Necessary	92.00 FL	*92.00 FL
53	1		*GARNISH ASSY-RR DE SIDE RH	Necessary	92.00 FL	*92.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*COVER-FR BUMPER UPR	Broken	476.00 FL	*476.00 FL
55	1		*CAP-FRONT HOOK	Not Necessary	5.00 FL	*- FL
56	1		*COVER-FR BUMPER,LWR	Broken	367.00 FL	*367.00 FL
57	1		*SKID PLATE-FR BUMPER	Not Necessary	55.00 FL	*- FL
58	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 FL	*- FL
59	1		*GRILLE-FRONT BUMPER	Not Necessary	96.00 FL	*- FL
60	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 FL	*- FL
61	1		*STRIP-FR BUMPER	Not Necessary	27.00 FL	*- FL
62	1		*COVER-RADIATOR GRILLE UPR	Not Necessary	46.00 FL	*- FL
63	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	61.00 FL	*- FL
64	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	98.00 FL	*- FL
65	1		*STIFFNER-FR BPR LWR	Not Necessary	123.00 FL	*- FL
66	1		*BRACKET-FR BUMPER SIDE,RH	Broken	13.00 FL	*13.00 FL
67	1		*AIR DUCT-FR BUMPER,RH	Broken	38.00 FL	*38.00 FL
68	1		*COVER-FR BUMPER FOG LAMP,RH	Cut	64.00 FL	*64.00 FL
69	1		*LAMP ASSY-FRONT FOG RH	Not Necessary	234.00 FL	*- FL
70	1		*PANEL-FENDER RH	Repair	401.00 FL	*- FL
71	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	56.00 FL	*- FL
72	1		*GARNISH ASSY-FNDR SIDE,RH	Cut	45.00 FL	*45.00 FL
73	1		*LAMP ASSY-HEAD,RH	Cut	1,845.00 FL	*1,845.00 FL
74	1		*RESERVOIR & PUMP ASSY-WASHER	Crushed	152.00 FL	*152.00 FL
75	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
76	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
77	1		*BODY PNL SEALANT	Necessary	80.00 FS	*40.00 FS
78	1		*RR CAMERA & TRUNK LID HDL ASSY (Supplementary)	Broken	758.00 FL	*758.00 FL
79	1		*BOARD ASSY-LUGGAGE (Supplementary)	Broken	399.00 FL	*399.00 FL
80	1		*TRIM ASSY-LUGGAGE SIDE RH (Supplementary)	Broken	232.00 FL	*232.00 FL
81	1		*TRIM ASSY-LUGGAGE SIDE LH (Supplementary)	Broken	232.00 FL	*232.00 FL
82	1		*SILENCER,FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
83	1		*EXTENSION ASSY-QTR OTR RR LH (Supplementary)	Bent	127.00 FL	*127.00 FL
84	1		*EXTENSION ASSY-QTR OTR RR RH (Supplementary)	Bent	127.00 FL	*127.00 FL
85	1		*BEAM COMPLETE-FR BUMPER (Supplementary)	Bent	544.00 FL	*544.00 FL
86	1		*BUMPER-T/GATE OVERSLAMP (Supplementary)	Crushed	3.00 FL	*3.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,600.00	12,466.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,490.00	2,473.20
Total Parts (\$\$)	14,110.00	9,992.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW (REAR) RR BUMPER, TAILGATE, RR END PNL & RR FLR PNL REPAIR ROOF PNL, LHR, FENDER & RHR FENDER	New	4,000.00	1,200.00
2	RENEW (FRT) FRT BUMPER & RHF FENDER, REPAIR RHF DOOR	New	1,600.00	600.00
3	RESPRAY RR BUMPER, RR END PNL, RR FLR PNL, TAILGATE, LHR FENDER, RHR FENDER, ROOF PNL- FRT BUMPER, RHF FENDER & RHF DOOR	New	3,500.00	2,100.00
4	REMOVE & REFIT TAILGATE COMPONENT	New	120.00	120.00
5	REMOVE & REFIT FUEL TANK ASSY	New	200.00	200.00
6	REMOVE & REFIT EXHAUST MUFFLER ASSY	New	400.00	400.00
7	REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT	New	120.00	120.00
8	REMOVE & REFIT ROOF LINING	New	200.00	0.00
9	CHECK WIRING ELECTRICAL WIRING & ADJUST HEADLAMP AIM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
11	RENEW RR WINDSCREEN GLASS	New	240.00	240.00
12	INSTALL RR WINDSCREEN SOLAR FILM	New	280.00	280.00
13	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00
14	SUPPLY RR NUMBER PLATE WITH CASING	New	80.00	50.00
15	REMOVE & REFIT REVERSE SENSOR	New	60.00	60.00
16	SUPPLY REAR IN-CAMERA	New	780.00	0.00
17	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	50.00
18	REPLACE REAR FLOOR PANEL, END PANEL & BOTH TAIL LAMP HOUSING (Supplementary)	New	1,600.00	1,600.00
19	SPRAY PAINT REAR FLOOR PANEL, END PANEL, BOTH TAIL LAMP HOUSING AND RH REAR FENDER (Supplementary)	New	1,400.00	1,400.00
Gross Labour Cost (\$)			14,930.00	8,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >