



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	The special is the first of the following property of the following pr	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name Reg No/Reg Date	LCV10800/ANG TECK LIP (WANG DELI) SMN3878L / 06/08/201
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage Chassis No	4 40007
AIG BUILDING SINGAPORE 079120	Engine No	G3LCKP067466
Contact No 64191000	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	27336	71 R 15 T T T T T T T T T T T T T T T T T T	
LAX00000	Credit	13/01/2021/ 16:06	BLE	261 / Edwin Caina	Qty Unit Price	Disc%	Amount
egat was a series of the serie	e de Companyo Santamago agresa. La participata de la participata de la companyo	Description of Good	is / Services	egin ar at same a 4 material and a supplied part would	policy appears	— T	4000.00
E PNT88000		1	DNI	DD ELD DNI 1015	0 x 3	1/2	199 ^{4000.00}
RENEW (REAR) RE	R BUMPER, TAILGATE, RR	LENU PNL &	KK PLK PNL 9			
E PNT88000	JOF PNL,	LHR, FENDER & RHR FEN	IDER			600	1600.00
PENEM (FRT) FRI	T ¹ BUMPER & RHF [®] FENDE	R			000	
REPAIR R		DOM EN G IIII					3500.00
				/ SENDED	2504 1		2100
RESPRAY I	RR' BUMPER	≀, RR END PNL, RR	FLR PNL ,	TAILGATE , LHR FENDER	· 330 X B		210-
RHR FEND	R , ROOF	PNL					
		FENDER & RHF DOOR	-	П	_		120.00
E PNT88000	DEETT TA	TIGATE COMPONENT		imai	2		
A 13900099	KELTI IN	(211				200.00
REMOVE &	REFIT FU	IEL TANK ASSY C	5) L		G 6	100	400.00
A 15900099							400.00
REMOVE &	REFIT EX	HUAST MUFLLER ASSY					120.00
E PNT88000		SID DOLOD TOTAL CAD	DET 0 CEAT	(pht)			200.00
	REFIT RK	FLR BOARD, TRIM, CAR	PEI & SEAT	C 1999			200.00
E PNT88000	DEELT BU	OF LINING					
A 54900099	KLIII NO	or Elivino					30.00
	ING ELEC	TRICAL SYSTEM & ADJ	UST HEADLA	MP AIM			
A 10028901						*	120.00
		NOSTIC CHECK USING	HI-SCAN PR	O TEST			
USING HI-	SCAN PRO	TEST					240.00
E PNT88000 RENEW RR	LITHICCOL	CN CLACC					2.000
M SUNDRY	MINDSCRE			1)			280.00
	R WINDSC	REEN SOLAR FILM	(Salas	agree			j
M SUNDRY				3			80.00
SUPPLY RE	WINDSCR	REEN SEALANT					Fa / 00 00
M SUNDRY							50/ 80.00
SUPPLY RI	R NUMBER	PLATE WITH CASING					

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

WIP No

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	LCV10800/ANG TECK LIP (WANG DELI) SMN3878L / 06/08/201			

Account No	Terms	Date/Time F		CSE	Oper	ator / Edwin	Caina	The second are proved that the part of	27336			
LAX00000	Credit	13/01/2021		BLE s / Services	201	, Euwin	Carna	Qty	Unit Price	Disc%	An	ount
E PNT88000	The second second	Description	o Good	S / Services	A. A. S.						1 2	60.00
	REFIT RE	VERSE SENSO	R								9 7027.1	780.00
M SUNDRY												/00.00
SUPPLY RE	AR IN-CA	MERA									to	120.00
M SUNDRY											50	
	I CORROS	ION ON AFFE	CTED AREA	.S							110	80.0
M SUNDRY											7	
SUPPLY BOI	DY PNL SE	EALANI										40.0
M SUNDRY	DADCE											
SUPPLY C&C M SUNDRY	BAUGE	_						1 2 7			201	30.0
Sundries		(5.4)	Lang	\mathcal{S}_{4}	P	50	∞ 5	70	\	* *		
M COVER-RR B	UMPER LW	IR (UM)		51111	($\widetilde{\mathbb{N}}$	7	1.00	366.00			292.8
CAP-RR HOO	K 7 3	CM	$\supset Q$	\mathcal{L} \mathcal{L}	Ш	JUU	الك	4.00		20.00		4.0 97.6
SKID PLATE	-RR BUMP		1	X NM				1.00	122.00		/	49.6
COVER-RR B	UMPER SI	DE UNDER		$1 \sim R$	D			1.00	152.00	20.00	/	121.6
MOULDING A	SSY-RR B	UMPER SIDE,	L (Yell2	$\frac{1}{1}$				1.00	152.00		/	121.6
MOULDING A	SSY-RR B	UMPER SIDE,	R (YeL.	/				1.00	111.00		ľ	88.8
		& R/REFL,L		1 X MM				1.00	111.00			88.8
LAMP ASSY- WIRING HAR		& R/REFL,R	MM AIM	1				1.00	245.00			196.0
I WIKING HAKI I BEAM-RR BUI		SK 2						1.00	419.00		/	335.2
BRACKET-RR		D MTC IH	XNN					1.00		20.00		5.6
BRACKET-RR			X MIN					1.00		20.00		4.0
BRACKET-RR		R MTG	X NM					1.00		20.00	_	5.6
STAY-RR BUI		1. 7.07						1.00		20.00		44.0
STAY-RR BU	MPER RH	1 / 67						1.00		20.00	/	44.00
ANTENNA ASS			MN R	R				1.00	32.00		_	25.60
BRACKET ASS				R				1.00		20.00	/	21.60
BRACKET ASS			X NI	V				1.00	189.00	20.00	•	302.40
ULTRASONIC			1 X MI					2.00	189.00			302.40
ULTRASONIC								1.00	1010.00		/	808.00
PANEL ASSY-	INIL UA	/ /	00		17				1010.00	20.00	•	
Confirm & acc	epted by											
9 //												
authorized sig	natory a	nd company s	tamp									

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

eg No : 199405410K	ESTIMATE	Owner Name & Vehicle Info
Invoice Name & Address AIG Asia Pacific Insurance Pte.	Reg No/Reg Date	LCV10800/ANG TECK LIP (WANG DELI) SMN3878L / 06/08/201 / 13327
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage Chassis No	KNAD6811VL6319558
AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No	KIA/STONIC 1.0 A SX BJ3 W SUNROOF MYW MOST YELLOW / WK SATURN BLACK

	WIP No	
occupt No. Terms Date/Time Printed CSE Operator	ina 27336 Amount	
12 /21 /2021 / 16:06 BLE 201 /		2.4
AX00000 Credit 13/01/2021/ 16:00 Description of Goods / Services	28.00 20.00	- 0
Description of Court	395.00 20.00	2.8
HINGE ASSY-TAIL GATE X RR	66.00 20.00	2.8
CLASS ASSY-TAIL GAIL / nin	66.00 20.00	0.8
PARTICULT/GATE UPRALM - 1 nn	51.00 20.00	0.8
CADNICH T/GATE UPK.KD	26.00 20.00	
LOGO ASSY-KIA SUB	38.00 20.00	0.4
EMPLEM_STONIC / // W	1.00 153.00 20.00	
FMOI EM TURRO G.D.1	21 00 20 00 72	2.8
DANIEL ASSY-TAIL GATE IKIM A DO	21 00 20 001	4.8
ATOTO TAIL GAIR URING	106 00 20 00	4.8
STRIKER ASSY-T/GATE X nn	75 94.00 20.00	5.2
LATCH ASSY-TAIL GATE X NO.	94.00 20.00	5.2
TETED ASSY-TAIL GAIE, LIT AND	204.00 20.00	
LIFTER ASSY-TAIL GATE, RH	345.00 20.00 276	6.0
PANEL ASSY-REAR FLOOR, RR		
DANEL ACCY-RACK ! PW / I/V	1.00	4.0
ACCY COVEDING SHELF	1.00	1.6
TOTM ASSY-RR IKANSVERSE . // Y TAK 1019	1.00	
MAT ASSY-LUGGAGE COVERING	2.00	
AMP ASSYLITENSE PLATE	1.00 608.00 20.00 486	
AMD ACCY_DEAR COMB INSIDE, LT //K	1.00 608.00 20.00	
ALCO ACCY DEAD (1)MB INSIDES IN /1 . PID	1.00 654.00 20.00 //	
AMD ACCV DEAR COMB UUISIULILII A	1.00 654.00 20.00	
LAMP ASST-REAR COMB OUTSIDE, RH	1.00 005.00 20.00	9.2
MUFFLER ASSY-REAR IN IN	1.00 49.00 20.00	1.2
NO WEAT DEAD	1 00 14.00 20.00	
	1 00 302.00 20.00	
MUFFLER ASSY-CENTER 1 nn	1 00 241.00 20.00	1.2
MOTOR & LINKAGE ASSY-REAR WER	1 00 39.00 20.00	
OLANG ACCY-WIDER RK	1.00 47.00 20.00	7.6
BLADE ASSISTANT ACCOUNTS OF MIDER / (M)	1.00 92.00 20.00 /	3.6
GARNISH ASSY-RR DR SIDE LH (Phuk 744)	1 00 92.00 20.00 /	3.6
GARNISH ASSY-RR DR SIDE RH (() Mk THY)	1.00 476.00 20.00 / 380).8
COVER-FR BUMPER UPR / PR		

Confirm & accepted by

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim CCV10800/ANG TECK LIP (WANG DELI) MANGE AND				

		Date Plans Date 44		CSE	Ope	rator		WIP No		
Account No	Terms	Date/Time Printe		BLE	261	/ Edwin Cai	na	27336		
LAX00000	Credit	13/01/2021/ 16:			LUI		Qty	Unit Price		Amount
		Description of G	oods /	Services			1.00	5.00	20.00	4.0
M CAP-FRONT	HOOK	X NN CD					1.00	367.00	20.00	293.6
M COVER-FR	BUMPER, L	WR 1 DER 1 X N	KI .				1.00		20.00	44.0
M SKID PLAT	E-FR BUM	" - "	MIM				1.00	32.00		25.0 76.8
LIP ASSY-	FRONT BU		, ,				1.00	96.00	20.00	259.
GRILLE-FR	ONT BUMP	~ 1/41					1.00	324.00	20.00	239.
GRILLE AS	SY-RADIA						1.00	27.00	20.00	36.
STRIP-FR	BUMPER	X NN ILLE UPR X NM					1.00		20.00	48.
COVER-RAD	IATOR GR			NAI			1.00	61.00	20.00	78.
MOULDING-	FRONT BU	MPER A/INTAKE	X M	ily			1.00	98.00	20.00	98.4
ABSORBER-	FRONT BO	MPER ENERGY	1				$\Box^{1.00}$	123.00	20.00	10.
STIFFNER-	-K RAK TI	STOE DH	· (=	< 5 P L		\sim	↑₹₽.% >	13.00	20.00	30.
BRACKET-F	C BOWNER	3100,7	(0	271 II			1.00		20.00	51.
AIR DUCT-F	HIMDED E	C LAMP PH	W CHI) [5]			7 (7.00)		20.00	187.
LAMP ASSY-	COONT FO	OG DH TO X NOT	$j \sim$				1.00	234.00		320.
		Si IV					1.00	401.00		44.
PANEL-FEND GUARD ASSY	EDONT L		<i>i</i> N				1.00	56.00	20.00	36.
GARNISH AS	CV ENDD	SIDE RH / CV	IT				1.00		20.00	1476.0
LAMP ASSY-	HEAD BH	CUT	•				1.00	1845.00		121.6
RESERVOIR	& PUMP A	ASSY-WASHER	/	CR4			1.00	152.00	20.00	121.0
	X Auto Coo					fere CLKK OD-1 EXCIS PIP GEL Market OA A A A A A A A A A A A A	My ALL	[1]21, 10·	110m	
Confirm & ag	Pensite to cepted by oresurvey belond display dama arts prices are nird party survoillegal modifi	of the following: ore/after spray painting aged part(s) during resurve e subject to confirmation rey is on a "Without Prejudic ication(s) is allowed item(s) must be resurveyed	e" basi s				7% GST on	Nett 24092.00 al Payable		24,092.00 1686.44 25,778.44

Validity of this estimate Replandays from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would ment on that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.