

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21000641/UGS3Q2
Date: 18/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100426998
Claimant Vehicle No :	SKT7764Y	Insured Vehicle No :	SKV1878G
Date of Loss:	13/01/2021	Nature of Claim:	TP
		Claim No:	9925842125SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT7764Y		
Make & Model:	NISSAN ALMERA, 1.5 (M)	Engine No:	HR15997075C
Reg. Date:	23/06/2015 (Man. Year: 2015)	Chassis No:	MNTBBAN17Z0004313
Colour:	Brown	Odometer:	164290 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,153.10	3,827.98	8,325.12	68.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,440.00	1,660.00	40.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,253.10	6,267.98	9,985.12	61.44
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	16,253.10	5,000.00	11,253.10	69.24
+ GST 7.00/7.00% (S\$)	1,137.72	350.00	787.72	69.24
Nett Amount (S\$)	17,390.82	5,350.00	12,040.82	69.24
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,652.00		

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 13/01/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	1,105.00 F	*846.00 FL
2	1		*BOOTLID REAR LOGO	Not Necessary	59.90 F	*- FL
3	1		*BOOTLID ALMERA EMBLEM	Necessary	62.00 F	*59.70 FL
4	1		*BOOTLID OUTER HANDLE	Not Necessary	399.00 F	*- FL
5	1		*BOOTLID INNER LOCK	Bent	166.00 F	*64.50 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	148.00 F	*103.90 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	305.00 F	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
9	1		*REAR BUMPER	Dented / Deformed	606.00 F	*518.80 FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	72.00 F	*- FL
11	1		*REAR BUMPER BRACKETS	O/S Dented	190.00 F	*86.60 FL
12	1		*REAR BUMPER SPONGE	Torn	165.00 F	*138.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*35.00 FL
14	1		*REAR BUMPER LOWER SKIRTING	Deformed	680.00 F	*450.00 FL
15	1		*REAR END PANEL	Dented	566.00 F	*458.20 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	228.00 F	*112.20 FL
17	1		*REAR END PANEL LOCK SENSOR	Not Necessary	351.00 F	*- FL
18	1		*TAILLAMPS	O/S Cracked	710.00 F	*264.40 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	530.00 F	*- FL
20	2		*REAR FENDERS	Repair	2,210.00 F	*- FL
21	1		*REAR FENDER INNER TRIMS	O/S Torn	732.00 F	*356.70 FL
22	1		*REAR FENDER UNDER COVER O/S	Distorted	98.20 F	*98.20 FL
23	1		*REAR FLOOR PANEL	Repair	1,140.00 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Torn	565.00 F	*350.00 FL
25	1		*REAR EXHAUST	Not Necessary	520.00 F	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	45.00 F	*- FL
27	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
29	1		*SET REAR FENDER UNDER COVER CLIPS O/S	Necessary	50.00 FS	*30.00 FS
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,153.10	4,222.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	394.22
Total Parts (\$\$)	12,153.10	3,827.98

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
5	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO SPRAY RUST PROOFING	New	100.00	60.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	980.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,180.00
Gross Labour Cost (S\$)			4,100.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >