



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103847
INV Date 02/06/2021
Reference CC4/LPC21000650/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 1265G
Insured Veh. XB 8740A
Claim No. 20/21/21/VC05/024127
Policy No. Z20VC05006215
Accident Date 11/01/2021
Inspection Date 13/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21000650/Kpa3q2

Date: 02/06/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XB 8740A	Veh. Inspected	SMU 1265G
Policy No.	Z20VC05006215	Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024127	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	13/01/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	MR2BE3BE700007945	Colour	METALLIC SILVER
Odometer	8587 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	9 mm
L/H Front Tyre	205/55 R16	MICHELIN	9 mm
R/H Rear Tyre	205/55 R16	MICHELIN	9 mm
L/H Rear Tyre	205/55 R16	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/01/2021	Inspection Date	13/01/2021
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 1265G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	367.70	367.70
10	FRONT BUMPER CLIP	NECESSARY	45.00	45.00
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	68.70	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	68.70	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	235.70	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	235.70	-
1	RH WING MIRROR (MOTOR)	CRACKED	1,855.50	1,855.50
1	RH WING MIRROR (GLASS)	SERVICEABLE	244.90	-
1	RH WING MIRROR (COVER)	MISSING	108.60	108.60
1	RH WING MIRROR SIGNAL LAMP	CRACKED	169.90	169.90
	LESS 25% DISCOUNT		-850.10	-636.68
			2,550.30	1,910.02
<u>LABOUR</u>				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(FRONT BUMPER ,RHF FENDER ,RHF DOOR AND RHS MIRROR).INCLUSIVE OF THE REPAIR OF FRONT BUMPER BRACKET LH AND FRONT BUMPER BRACKET RH .		800.00	300.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(FRONT BUMPER ,RHF FENDER ,RHF DOOR AND RHS MIRROR).		800.00	280.00
	TO CHECK WIRING .		50.00	20.00
	TO DO WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,770.00	600.00
GRAND TOTAL			4,320.30	2,510.02
RECOMMENDED COST OF REPAIRS				2,510.02

Report Ref No. CC4/LPC21000650/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 1265G

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



TOYOTA MOTOR CORPORATION
MODEL 4E-210R-GE-XGPZ
ENGINE 1.8L-FAE 1598 mL
FRAME NO. MK2B3BE700007943
COLOR TRIM PLANT DIM (kg)
ID4 FB20 Z35
INVENTORY K313 - 02A JAN 20
MFG: TOYOTA MOTOR THAILAND CO., LTD. MADE IN THAILAND



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 1265G

RE-INSPECTION

