

Wapac



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMU 1265 G

Parts	(a) Cost / List Price Items	\$	<u>3,400.40</u>
	Plus/Less 25%	\$	<u>850.10</u>
	Total of Cost / List	\$	<u><u>2,550.30</u></u>
	(b) Nett Price Items		_____
	Less		_____
	Total of Nett Item		_____
	(c) Special Nett Items		_____
Total Parts Cost		\$	<u><u>2,550.30</u></u>
Labour		\$	<u><u>1,770.00</u></u>
Total		\$	<u><u>4,320.30</u></u>

The above total will be subjected to 7% G.S.T.

*Not Authorized
Mechanic B4 paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 13/1/21 at 3:20pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Pe Date: 13/1/21

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N



ESTEEM

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : SMU 1265 G
Make & Model : TOYOTA ALTIS
Chassis No : MR2BE3BE700007945

Submit By : JENNY
Year Manufacture : 2020 JULY
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>GM</i>	1	\$367.70		✓
2	Front bumper clip <i>MR</i>	10	\$45.00		✓
3	Front bumper side retainer LH <i>SM</i>	1	\$68.70		X
4	Front bumper side retainer RH <i>SM</i>	1	\$68.70		X
5	Front bumper bracket LH <i>R</i>	1	\$235.70		X
6	Front bumper bracket RH <i>R</i>	1	\$235.70		X
7	RH wing mirror ^{with} (motor) <i>CM</i>	1	\$1,855.50		✓
8	RH wing mirror (glass) <i>SM</i>	1	\$244.90		X
9	RH wing mirror (cover) <i>MS</i>	1	\$108.60		✓
10	RH wing Mirrir signal lamp <i>CM</i>	1	\$169.90		✓
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

