



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4433A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	957.40	-
1	REAR BOOTLID LH REFLECTOR LAMP	TO REPAIR SEE LABOUR	466.40	-
1	REAR BOOTLID MECHANISM LOCK	TO REPAIR SEE LABOUR	179.70	-
1	REAR BOOTLID WEATHER STRIP	REUSE	107.70	-
1	REAR LH TAILLAMP	SERVICEABLE	509.40	-
1	REAR BUMPER	CRACKED	1,674.80	998.00
1	REAR BUMPER CENTER BRACKET	SERVICEABLE	15.10	-
2	REAR BUMPER REFLECTOR L/R	SERVICEABLE	102.00	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	537.30	-
2	REAR BUMPER SIDE BRACKET L/R	SERVICEABLE	60.20	-
2	REAR BUMPER SIDE RETAINER L/R	SERVICEABLE	72.20	-
1	REAR END PANEL INNER TOP GARNISH	REUSE	85.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	505.10	-
	LESS 20% DISCOUNT		-1,054.48	-199.60
			4,217.92	798.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR LH TAILLAMP CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
			420.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	60.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.	NOT NECESSARY	80.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	200.00

Report Ref No. CS3/AIG20011121/R1td3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID LH REFLECTOR LAMP, REAR BOOTLID MECHANISM LOCK, REAR BUMPER REINFORCEMENT AND REAR END PANEL.		1,000.00	200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	80.00	-
			2,280.00	460.00
<b>GRAND TOTAL</b>			<b>6,917.92</b>	<b>1,288.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CS3/AIG20011121/R1td3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.