

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000651/QPA3Q2
Date: 09/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070168868
Claimant Vehicle No :	SLJ6515Y	Insured Vehicle No :	GBD9794M
Date of Loss:	10/01/2021	Nature of Claim:	TP
		Claim No:	7027078914SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6515Y		
Make & Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Engine No:	1NZR435751
Reg. Date:	20/12/2016 (Man. Year: 2016)	Chassis No:	NKE1657137899
Colour:	Silver	Odometer:	308578 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,770.88	3,843.47	2,927.41	43.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,070.00	2,320.00	52.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,160.88	5,913.47	5,247.41	47.02
Approved Total (Overridden) (S\$)		4,750.00		

(S\$)	11,160.88	4,750.00	6,410.88	57.44
+ GST 7.00/7.00% (S\$)	781.26	332.50	448.76	57.44
Nett Amount (S\$)	11,942.14	5,082.50	6,859.64	57.44
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		5,614.50		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 13/01/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Crumpled	1,059.84 FL	*780.00 FL
2	1		*REAR BOOT OUTER CHROME HANDLE	Cracked	420.00 FL	*295.16 FL
3	1		*REAR BOOT TOYOTA LOGO	Necessary	50.00 FL	*50.00 FL
4	1		*REAR BOOT COROLLA EMBLEM	Necessary	40.00 FL	*40.00 FL
5	1		*REAR BOOT AXIO EMBLEM	Necessary	30.00 FL	*30.00 FL
6	1		*REAR BOOT HYBRID EMBLEM	Necessary	60.00 FL	*60.00 FL
7	1		*REAR BOOT WEATHERSTRIP	Crumpled	226.00 FL	*226.00 FL
8	1		*REAR BOOT LOCK	Jammed	418.00 FL	*180.00 FL
9	1		*REAR BOOT LOCK CATCH	Serviceable	60.00 FL	*- FL
10	1		*REAR BOOT BACK TRIM COVER	Serviceable	226.00 FL	*- FL
11	2		*REAR BOOT HINGES	Bent	156.00 FL	*156.00 FL
12	1		*REAR BOOT LH INNER SIDE TRIM COVER	Serviceable	550.00 FL	*- FL
13	2		*REAR TAILLAMPS	Cracked	1,680.00 FL	*1,092.00 FL
14	1		*REAR END PANEL	Dented	850.00 FL	*682.10 FL
15	1		*REAR END PANEL TOP COVER	Crumpled	320.00 FL	*226.70 FL
16	1		*REAR END PANEL BACK COVER	Serviceable	240.00 FL	*- FL
17	1		*REAR BUMPER	Crumpled	780.00 FL	*780.00 FL
18	1		*REAR BUMPER RH ARM	Serviceable	56.00 FL	*- FL
19	1		*REAR BUMPER LH ARM	Serviceable	56.00 FL	*- FL
20	1		*REAR BUMPER LH RETAINER	Broken	180.00 FL	*110.00 FL
21	1		*REAR BUMPER ANTENA	Serviceable	380.00 FL	*- FL
22	1		*R/R TAILLAMP RETAINER	Broken	35.00 FL	*15.00 FL
23	1		*R/L TAILLAMP RETAINER	Broken	35.00 FL	*15.00 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
25	1		*SET END PANEL GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
26	1		*SET BODY SEALANT	Necessary	400.00 FS	*40.00 FS
27	1		*SET REVERSE SENSOR	Shorted	240.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,747.84	5,027.96
- List Item Discount on L Items 25.00/25.00% (\$)	1,976.96	1,184.49
Total Parts (\$)	6,770.88	3,843.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER ,REAR BOOT AND CUTTING OUT REAR END PANEL TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,500.00	1,000.00
2	TOWING FEE	New	50.00	0.00
3	TO RESPRAY REAR BUMPER ,END PANEL,SPARE TYRE PANEL ,REAR BOOT	New	1,500.00	1,000.00
4	TO APPLY RUST PROOFING ON ALL DAMAGED PARTS	New	180.00	40.00
5	TO REMOVE SPEAKER BOARD ,ROOF LINING TO ENABLE REPAIRS	New	280.00	0.00
6	TO CHECK WIRING SYSTEM	New	280.00	30.00
7	TO CONDUCT A STANGARA OF OPEARTING PROCEDURES POST SCANT TEST AS A REQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
8	TO DEACTIVATE AND ACTIVATE HYBRID HIGH VOLTAGE BATTERY AS A SAFETY PRECAUTIONS	New	300.00	0.00
Gross Labour Cost (S\$)			4,390.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >