

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000656/R1VF3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00017852005

**Claimant
Vehicle No :** SKN5588J

**Insured
Vehicle No :** GBD7272R

Date of Loss: 11/01/2021

Nature of
Claim: TP

Claim
No: SNM21D200185/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN5588J**

Make & Model: BMW X2, 1.5 SDRIVE18I (A)

Engine No: 36255615B38A15A

Reg. Date: 29/04/2019 (Man. Year: 2019)

Chassis No: WBAYH12050EM94256

Colour: Blue

Odometer: 22948 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R19

Rear Tyre Size: 225/45R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,642.65	3,848.20	1,794.45	31.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,426.00	4,238.00	1,188.00	21.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,068.65	8,086.20	2,982.45	26.95
+ GST 7.00/7.00% (S\$)	774.81	566.03	208.78	26.95
Nett Amount (S\$)	11,843.46	8,652.23	3,191.23	26.95

INSPECTION

Date of Assignment: 13/01/2021

Date Inspected: 14/01/2021 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2021)
Parts:	M1-SUV	BMW X2 1.5 SDRIVE18I (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN5588J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH SIDE PANEL	Bent	667.35 FS	*667.35 FS
2	1		*FRT BUMPER TOP CARRIER	Not Necessary	375.85 FS	*- FS
3	1		*IMPACT ABSORBER TOP (M)	Not Necessary	60.45 FS	*- FS
4	1		*FRT BUMPER PANEL PRIMED (M PDC/PMA)	Repair	1,288.15 FS	*- FS
5	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	3,086.85 FS	*3,086.85 FS
6	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
7	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
					Total Parts (S\$)	5,642.65 3,848.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER,FRONT LH FENDER & ATTACHMENT ITEM CAUSE BY ACCIDENT	New	2,550.00	1,700.00
2	TO SPRAY PAINT FRONT BUMPER,FRONT LH FENDER	New	1,923.00	1,730.00
3	TO REPLACE LEFT HEADLIGHT	New	481.00	408.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
5	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	150.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			5,426.00	4,238.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >