

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000659/EVF3Q2

**Date:** 19/02/2021

### REFERENCE

Insured/Claimant:	CHEW CHUAN MUI	Policy No:	2100421707	
Date of Loss:	12/01/2021	Nature of Claim:	OD	Claim No: 0953675857SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU3670E			
Make & Model:	MITSUBISHI LANCER, 1.3 (A)		Engine No:	4A92CA0564
Reg. Date:	22/07/2015 (Man. Year: 2015)		Chassis No:	JMYSRCY1AFU005125
Colour:	Grey		Odometer:	60393 km
Engine Capacity:	1590 cc			
Market Value/New Car Price:	S\$44,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,882.32	3,683.66	198.66	5.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	3,330.00	1,250.00	27.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,462.32</b>	<b>7,013.66</b>	<b>1,448.66</b>	<b>17.12</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	7,862.32	6,413.66	1,448.66	18.43
<b>+ GST 7.00/7.00% (S\$)</b>	550.36	448.96	101.40	18.42
<b>Nett Amount (S\$)</b>	<b>8,412.68</b>	<b>6,862.62</b>	<b>1,550.06</b>	<b>18.43</b>

### INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd  
(Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Dented	913.00 FL	*913.00 FL
2	1		*HINGE,HOOD,LH	Bent	64.00 FL	*64.00 FL
3	1		*HINGE,HOOD,RH	Bent	64.00 FL	*64.00 FL
4	8		*CLIP,HOOD INSULATOR	Necessary	24.00 FL	*24.00 FL
5	1		*WEATHERSTRIP,HOOD	Not Necessary	18.00 FL	*- FL
6	1		*WEATHERSTRIP,HOOD,FR	Not Necessary	31.00 FL	*- FL
7	1		*LATCH,HOOD	Not Necessary	58.00 FL	*- FL
8	1		*FENDER,FR RH	Dented	688.00 FL	*688.00 FL
9	1		*BRACKET,FR FENDER,RH	Not Necessary	16.00 FL	*- FL
10	1		*SHIELD,FR FENDER,FR RH	Torn	122.00 FL	*122.00 FL
11	1		*HEADLAMP ASSY,RH	Broken	846.00 FL	*846.00 FL
12	1		*FACE,FR BUMPER	Broken	1,040.00 FL	*1,040.00 FL
13	1		*GARNISH,FR BUMPER,RH	Not Necessary	39.00 FL	*- FL
14	1		*GRILLE,FR BUMPER	Not Necessary	96.00 FL	*- FL
15	1		*BRACKET,FR BUMPER SIDE,RH	Broken	17.00 FL	*17.00 FL
16	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
17	1		*SUPPORT,FR BUMPER, RH (Supplementary)	Broken	13.00 FL	*13.00 FL
18	1		*TANK, WINDSHIELD WASHER (Supplementary)	Crushed	90.00 FL	*90.00 FL
19	15		*CLIP,RR BUMPER (Supplementary)	Necessary	45.00 FL	*45.00 FL
20	1		*PANEL, HEADLAMP SUPPORT,UPR (Supplementary)	Bent	296.00 FL	*296.00 FL
21	1		*REINFORCEMENT,FR BUMPER (Supplementary)	Bent	529.00 FL	*529.00 FL
22	1		*COVER,FR BUMPER GRILLE (Supplementary)	Missing	4.00 FL	*4.00 FL
23	1		*CLIP,HOOD LOCKING (Supplementary)	Necessary	3.00 FL	*3.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,036.00</b>	<b>4,778.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$)</b>	<b>1,153.68</b>	<b>1,094.34</b>
<b>Total Parts (\$)</b>	<b>3,882.32</b>	<b>3,683.66</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	*OD/TP Case (Insurer)	-	0.00
<b>Sub Total (\$\$)</b>			<b>0.00</b>	<b>0.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW FRT BUMPER,BONNET & RHF FENDER.REPAIR HEADLAMP SUPPORT PNL,RHF DOOR & LHF FENDER	New	2,250.00	1,350.00
2	RESPRAY FRT BUMPER,BONNET,RHF FENDER,RHF DOOR,LHF FENDER & HL SUPPORT PNL	New	2,100.00	1,750.00
3	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,580.00</b>	<b>3,330.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >