



AIG - OD CLAIM
Survey: 14/01/21
LKK - STEVE

VEHICLE NO : SKU 3670E

MODEL : MIT/LANCER EX 1.6 GLS 4AT

WIP : 61811

Material	:	\$	<u>3,663.66</u>
Labour	:	\$	<u>3,350.00</u>
Sub-Total	:	\$	<u>7,013.66</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>6,413.66</u>
GST 7%	:	\$	<u>448.96</u>
Grand Total	:	\$	<u>6,862.62</u>
Finalise By/Date : <u>Larry on 08/02/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (week end)

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV03951/Chew Chuan Mui Reg No/Reg Date SKU3670E / 22/07/2015 Date In/Mileage 15/01/2021/ 60393 Chassis/Package JMYSRCY1AFU005125 /DC17RP(F) Engine No 4A92CA0564 Make/Model MIT/LANCER EX 1.6 GLS 4A/T (F05) Colour/Trim U01 / BK
15/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 11:23	BLE	884 / Lauro Songcuan	61811
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, BONNET AND RH FRONT FENDER, REPAIR HEADLAMP SUPPORT PANEL, RH FRONT DOOR & LH FRONT FENDER					1350.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER, BONNET, RH FRONT FENDER, RH FRONT DOOR AND LH FRONT FENDER					1750.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					80.00 ?
M SUNDRY SUNDRIES					20.00 ✓
X EXC EXCESS					-600.00
X HOOD ✓		1.00	913.00	23.00	703.01 ✓
X HINGE,HOOD,LH ✓		1.00	64.00	23.00	49.28 ✓
X HINGE,HOOD,RH ✓		1.00	64.00	23.00	49.28 ✓
X CLIP,HOOD INSULATOR ✓		8.00	3.00	23.00	18.48 ✓
X FENDER,FR RH ✓		1.00	688.00	23.00	529.76 ✓
X HEADLAMP ASSY,RH ✓		1.00	846.00	23.00	651.42 ✓
X FACE,FR BUMPER ✓		1.00	1040.00	23.00	800.80 ✓
X BRACKET,FR BUMPER SIDE,RH ✓		1.00	17.00	23.00	13.09 ✓
X SUPPORT,FR BUMPER,RH ✓		1.00	13.00	23.00	10.01 x
X TANK,WINDSHIELD WASHER ✓		1.00	90.00	23.00	69.30 x
X SHIELD,FR FENDER,FR RH ?		1.00	122.00	23.00	93.94 ?
X CLIP,RR BUMPER		15.00	3.00	23.00	34.65 x
X PANEL,HEADLAMP SUPPORT,UPR		1.00	296.00	23.00	227.92 x
X REINFORCEMENT,FR BUMPER		1.00	529.00	23.00	407.33 x
X COVER,FR BUMPER GRILLE		1.00	4.00	23.00	3.08 x
X CLIP,HOOD LOCKING		1.00	3.00	23.00	2.31 x



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/01/2021	Cust No/Name	KCV03951/Chew Chuan Mui
	Reg No/Reg Date	SKU3670E / 22/07/2015
	Date In/Mileage	15/01/2021/ 60393
	Chassis/Package	JMYSRCY1AFU005125 /DC17RP(F)
	Engine No	4A92CA0564
	Make/Model	MIT/LANCER EX 1.6 GLS 4A/T (F05)
	Colour/Trim	U01 / BK

CYCI

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 11:23	BLE	884 / Lauro Songcuan	61811

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 14.01.2021 DOA: 12.01.2021 05 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	3,663.66	Nett	6,413.66
Labour	3,250.00	7% GST on	448.96
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	6,862.62
Sundry/Others	-500.00		
Total(w/o GST)	6,413.66		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SKU 3670 E

	<u>Material</u>	<u>Cost \$</u>	
1	Support, FR Bumper, RH	13.00	/ BR
2	Tank, Windschild Washer	90.00	/ CRU
3	Clip, RR Bumper (15 pcs)	45.00	/ nec
4	Panel, Headlamp Support, UPR	296.00	/ BT
5	Reinforcement, FR Bumper	529.00	/ BT
6	Cover, FR Bumper Grille	4.00	/ MIS
7	Clip, Hood Locking	3.00	/ nec
		980.00	
	23% Discount	225.40	
		754.60	
	7% GST	52.82	
	Total	807.42	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SKU3670E

WIP: 61811

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel Headlamp Support with PR	? / SUPP		/ BT	
2	REINFORCEMENT FOR BUMPER	? / SUPP		/ BT	
3	SUPPORT - FOR BUMPER RH	? / SUPP		/ MJS	
4	COVER FOR BUMPER GRILLE RH	? / SUPP		/ MJS	} Steve 18/11/21
5	TANK WINDSHIELD WASHWATER	? / SUPP		/ CK4	
6	PROTECTOR FOR WINDSHIELD: RH RH	? / SUPP		/ CK4	
7	SHIELD FOR BENDER SPRING, FOR RH	? / SUPP		/ TM	
8	CLIP, SPRING SPRING 215	? / SUPP		/ PK	
9	CLIP, HOOD HOLDING (x1)	? / SUPP		/ PK	
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	20/11/21	Steve
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: MIT EX

SURVEYOR: STEVE

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	CY1A 2015MY

8KJ8670F

Before using MUT-3 ver unit to check all the found

2021.01.26

</					

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	CY1A 2015MY

3K1J8676E

After Repair to Cam out Diagnostic check on electronic control system

is to use POST-34 not use to Bridge all the bond
 is to use Done

2021.01.26

All DTCS

2021.01.26

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MP/IGDI/DIESEL	GAS_0E640000		No DTCS		
AT/CVT/A-MT/T-C-SST	AT4_10801005		No DTCS		
ABS/ASC/ASTC/WSS	ABS_4088000E		No DTCS		
SRS-AIR BAG	ORC_81087196		No DTCS		
Air Conditioner	AC_80080006		No DTCS		
ETACS (Can't see P/N on ECU body)	ETACS_83040900		No DTCS		
Meter	MTR_84084000		No DTCS		
Steering Angle Sensor	GS_SAS_47000100		Non-equipped System or Communication Error		
LIN (Can see P/N on ECU body)	ETACS_83040900		Non-target System		
KOS/IMMO/Keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY		No DTCS		
AFS/ACL/Leveling	AFS_90080000		Non-equipped System or Communication Error		