LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21000665/R1TF3E2

29/01/2021 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900168888 **Claimant Vehicle**

SKW741T Insured Vehicle No: **SBX777S** No:

Date of Loss: 11/01/2021 Nature of Claim: TP Claim No: 4315352742SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW741T**

Make & Model: HYUNDAI ELANTRA, 1.6 (A) G4FGFU036897 Engine No:

Reg. Date: 16/10/2015 (Man. Year: 2015) Chassis No: KMHDH41CMGU641506

Colour: Odometer: 122568 km White

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/01/2021

Car Laboratories Pte Ltd (HQ)

1 BUKIT BATOK CRESCENT, #04-56 WCEGA Date Inspected: 14/01/2021 Inspected At:

PLAZA

Singapore 658064

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL DENISE TAY KWEE CHENG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1	*REAR BUMPER	Deformed	0.00 F	*-F
3	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1	*REAR BUMPER BRACKET	Necessary	0.00 F	*-F
5	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1	*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
7	1	*REAR BUMPER DAMPER	Bent	0.00 F	*- F
8	1	*REAR BUMPER LOWER SPOILER	Missing	0.00 F	*- F
9	1	*REVERSE SENSOR	Not Working	0.00 F	*- F
10	1	*REAR END PANEL	Bent	0.00 F	*- F
11	1	*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
12	1	*REAR LH TAILLAMP	Cracked	0.00 F	*- F
13	1	*BOOTLID	Bent	0.00 F	*- F
14	3	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
15	1	*BOOTLID LAMP RH	Cracked	0.00 F	*- F
16	1	*BOOTLID LOCK	Bent	0.00 F	*- F
17	1	*BOOTLID RUBBER	Necessary	0.00 F	*- F
18	1	*BOOTLID INNER BOARD	Cut	0.00 F	*- F
19	1	*SPARE TYRE PANEL	Repair	0.00 F	*- F
20	1	*REAR LH CHASSIS MEMBER	Bent	0.00 F	*-F
F=Fr	anchise part.		Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >