

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21000667/EVF3E2  
**Date:** 09/03/2021

### REFERENCE

Insured/Claimant: JULIANNA NG YEN HONG Policy No: 2070006470  
Date of Loss: 12/01/2021 Nature of Claim: OD Claim No: 1670189114SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR6729T**  
Make & Model: MITSUBISHI ATTRAGE, 1.2 (A) Engine No: 3A92UJK2598  
Reg. Date: 17/01/2020 (Man. Year: 2019) Chassis No: MMBSTA13AKH004810  
Colour: Grey Odometer: 14864 km  
Engine Capacity: 1193 cc  
Market Value/New Car Price: S\$62,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,032.91	10,337.16	2,695.75	20.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,945.00	11,020.00	2,925.00	20.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,977.91</b>	<b>21,357.16</b>	<b>5,620.75</b>	<b>20.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,888.45</b>	<b>1,495.00</b>	<b>393.45</b>	<b>20.83</b>
<b>Nett Amount (S\$)</b>	<b>28,866.36</b>	<b>22,852.16</b>	<b>6,014.20</b>	<b>20.83</b>

### INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 12/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 20.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*HEADLAMP ASSY, LH	Broken	660.00 FL	*660.00 FL
3	1		*HEADLAMP ASSY, RH	Broken	660.00 FL	*660.00 FL
4	1		*LAMP ASSY, COMB, RR RH	Broken	335.00 FL	*335.00 FL
5	1		*LAMP ASSY, LICENSE PLATE	Broken	51.00 FL	*51.00 FL
6	1		*TANK, WINDSHIELD WASHER	Not Necessary	74.00 FL	*- FL
7	1		*CAP, WASHER TANK FILLER	Not Necessary	7.00 FL	*- FL
8	1		*HORN	Not Necessary	79.00 FL	*- FL
9	1		*PIPE, EXHAUST TAIL	Not Necessary	603.00 FL	*- FL
10	1		*SEAL RING, EXHAUST PIPE	Not Necessary	8.00 FL	*- FL
11	1		*HANGER, EXHAUST MUFFLER	Not Necessary	22.00 FL	*- FL
12	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
13	1		*COVER, HEADLAMP SUPT PANEL	Broken	62.00 FL	*62.00 FL
14	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
15	1		*BRACKET, FR BUMPER, RH	Broken	13.00 FL	*13.00 FL
16	1		*BRACKET, FR BUMPER, LH	Broken	13.00 FL	*13.00 FL
17	1		*AIR DAM, SIDE, FR RH	Not Necessary	18.00 FL	*- FL
18	1		*AIR DAM, SIDE, FR LH	Not Necessary	18.00 FL	*- FL
19	1		*GRILLE, FR UNDER	Broken	165.00 FL	*165.00 FL
20	1		*GARNISH, FR BUMPER, RH	Not Necessary	127.00 FL	*- FL
21	1		*BRACKET, RR BUMPER, LH	Not Necessary	28.00 FL	*- FL
22	1		*BRACKET, RR BUMPER, RH	Broken	28.00 FL	*28.00 FL
23	1		*FACE, RR BUMPER	Dented	748.00 FL	*748.00 FL
24	1		*GRILLE, RADIATOR	Broken	554.00 FL	*554.00 FL
25	1		*HOOD	Dented	734.00 FL	*734.00 FL
26	1		*INSULATOR, HOOD	Crushed	177.00 FL	*177.00 FL
27	1		*HINGE, HOOD, LH	Not Necessary	56.00 FL	*- FL
28	1		*HINGE, HOOD, RH	Not Necessary	56.00 FL	*- FL
29	1		*DAM, HOOD	Not Necessary	20.00 FL	*- FL
30	1		*LATCH, HOOD	Not Necessary	69.00 FL	*- FL
31	1		*FENDER, FR RH	Dented	497.00 FL	*497.00 FL
32	1		*FENDER, FR LH	Repair	497.00 FL	*- FL
33	1		*PANEL ASSY, FR END	Dented	1,055.00 FL	*1,055.00 FL
34	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	65.00 FL	*- FL
35	1		*PANEL, QTR, OTR RH	Dented	763.00 FL	*763.00 FL
36	1		*PANEL, RR COMB LAMP HSG, RH	Dented	60.00 FL	*60.00 FL
37	1		*REINF, RR PILLAR, RH	Not Necessary	126.00 FL	*- FL
38	1		*FLOOR, RR	Dented	956.00 FL	*956.00 FL
39	1		*PANEL, RR END	Dented	425.00 FL	*425.00 FL
40	1		*GLASS, RR WINDOW	Not Necessary	544.00 FL	*- FL
41	2		*STOPPER, WINDSHIELD GLASS	Necessary	6.00 FL	*6.00 FL
42	2		*SPACER, RR WINDOW	Necessary	18.00 FL	*18.00 FL
43	1		*WEATHERSTRIP, TRUNK LID	Crushed	157.00 FL	*157.00 FL
44	1		*PANEL, TRUNK LID	Dented	791.00 FL	*791.00 FL
45	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 FL	*- FL
46	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 FL	*- FL
47	1		*LATCH, TRUNK LID	Not Necessary	218.00 FL	*- FL
48	1		*SHIELD, FR WHEELHOUSE, RH	Not Necessary	98.00 FL	*- FL
49	1		*GARNISH, RR END PANEL	Not Necessary	336.00 FL	*- FL
50	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
51	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*TRIM, RR END	Torn	66.00 FL	*66.00 FL
53	1		*BOARD, TRUNK ROOM FLOOR	Torn	195.00 FL	*195.00 FL
54	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
55	1		*EMBLEM ECO (RH)	Necessary	17.00 FS	*17.00 FS
56	1		*CONDENSER ASSY, A/C REFRIGE (Supplementary)	Bent	758.00 FL	*758.00 FL
57	1		*PANEL, AIR GUIDE (Supplementary)	Broken	112.00 FL	*112.00 FL
58	1		*PANEL, AIR GUIDE, RH (Supplementary)	Broken	11.00 FL	*11.00 FL
59	1		*PANEL, AIR GUIDE, LH (Supplementary)	Broken	11.00 FL	*11.00 FL
60	1		*SILENCER, FLOOR (Supplementary)	Necessary	14.00 FL	*14.00 FL
61	1		*MUD GUARD, RR RH (Supplementary)	Broken	41.00 FL	*41.00 FL
62	1		*SHIELD, RR WHEELHOUSE, RH (Supplementary)	Broken	40.00 FL	*40.00 FL
63	2		*CLIPS (Supplementary)	Necessary	6.00 FL	*6.00 FL
64	1		*LLC 4L (Supplementary)	Necessary	26.00 FL	*26.00 FL
65	15		*CLIPS (Supplementary)	Necessary	60.00 FL	*60.00 FL
66	6		*CLIPS (Supplementary)	Necessary	18.00 FL	*18.00 FL
67	1		*GARNISH, FR PILLAR,RH (Supplementary)	Broken	30.00 FL	*30.00 FL
68	1		*COVER,FR BUMPER (Supplementary)	Crushed	12.00 FL	*12.00 FL
69	4		*GROMMET (Supplementary)	Necessary	12.00 FL	*12.00 FL
70	2		*CLIPS (Supplementary)	Necessary	6.00 FL	*6.00 FL
71	1		*EMBLEM ECO (LH) (Supplementary)	Necessary	17.00 FS	*17.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,410.00</b>	<b>12,915.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$)</b>	3,377.09	2,577.84
<b>Total Parts (\$)</b>	<b>13,032.91</b>	<b>10,337.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT BUMPER, BONNET, FRT RH FENDER, SUPPORT PANEL, BODY KIT & AFFECTED AREA. REPAIR ON FRT LH FENDER & FRT RH DOOR	New	3,150.00	1,800.00
2	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, FRT RH DOOR & SUPPORT PANEL	New	2,100.00	1,750.00
3	REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR RH TAIL LAMP PANEL, REAR RH FENDER & AFFECTED AREA	New	3,600.00	3,000.00
4	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR RH FENDER, REAR RH TAIL LAMP PANEL & BODY KIT	New	2,450.00	2,275.00
5	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
6	TO TOP UP AIR CON GAS	New	80.00	80.00
7	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
8	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
9	TO REMOVE & REAR SEAT FOR FACILITATE REPAIR	New	120.00	120.00
10	TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL	New	120.00	120.00
11	TO REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	240.00	240.00
12	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
13	TO APPLY BODY SEALANT ON AFFECTED PANEL	New	80.00	80.00
14	PERFORM RUST PREVENTION	New	80.00	80.00
15	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
16	TO SUPPLY C & C EMBLEM	New	40.00	40.00
17	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
18	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
19	TO REPLACE REAR EXHAUST MUFFLER	New	450.00	0.00
20	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR. (Supplementary)	New	225.00	225.00
21	SUPPLY ONE SET OF REVERSE SENSOR (Supplementary)	New	220.00	220.00
22	RESPRAY LH REAR FENDER (Supplementary)	New	350.00	350.00
			<b>Gross Labour Cost (\$\$)</b>	<b>13,945.00</b>
				<b>11,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >