

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21000669/UTF3E2

Date: 24/02/2021

REFERENCE

Insured/Claimant:	LIN WEIXIONG	Policy No:	D18MPC0002312		
Date of Loss:	12/01/2021	Nature of Claim:	OD	Claim No:	MPC2021D0000267

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7313D		
Make & Model:	HYUNDAI TUCSON, 1.6 GLS T-GDI DCT 2WD (A)	Engine No:	G4FJHU314621
Reg. Date:	09/11/2017 (Man. Year: 2017)	Chassis No:	KMHJ3812VJU606254
Colour:	Grey	Odometer:	55903 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60R17	Rear Tyre Size:	235/60R17
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,233.92	8,893.92	5,340.00	37.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,910.00	3,890.00	2,020.00	34.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,143.92	12,783.92	7,360.00	36.54
Approved Total (Overridden) (S\$)		10,200.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	19,543.92	9,600.00	9,943.92	50.88
+ GST 7.00/7.00% (S\$)	1,368.07	672.00	696.07	50.88
Nett Amount (S\$)	20,911.99	10,272.00	10,639.99	50.88

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Feb 2021)

Parts: M1-SUV HYUNDAI TUCSON 1.6 GLS T-GDI DCT 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT7313D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,452.00 FL	*- FL
2	1		*FRONT GRILLE & CHROME MOULDING	Scratched	953.00 FL	*953.00 FL
3	1		*FRONT GRILLE H EMBLEM	Necessary	35.00 FL	*35.00 FL
4	1		*FRONT BUMPER	Repair	494.00 FL	*- FL
5	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
6	1		*FRONT BUMPER LOWER GARNISH	Scratched	371.00 FL	*371.00 FL
7	10		*FRONT BUMPER LOWER GARNISH CLIPS	Necessary	35.00 FL	*35.00 FL
8	2		*FRONT O/S & N/S FENDER WHEEL GARNISH	Scratched	260.00 FL	*260.00 FL
9	16		*FRONT O/S & N/S FENDER GARNISH CLIPS	Necessary	56.00 FL	*56.00 FL
10	1		*FRONT O/S & N/S DOOR	O/s Dented/N/s Repair	2,824.00 FL	*1,412.00 FL
11	1		*SET FRONT O/S & N/S DOOR FRAME STICKER	O/s Necessary	72.00 FL	*36.00 FL
12	1		*FRONT O/S DOOR LOCK OUTER HANDLE (CHROME) WITH SENSOR	Cracked	224.00 FL	*224.00 FL
13	1		*FRONT O/S DOOR LOCK OUTER HANDLE SEAL	Necessary	14.00 FL	*14.00 FL
14	1		*FRONT O/S DOOR GLASS OUTER MOULDING	Bent	75.00 FL	*75.00 FL
15	1		*FRONT WINDSCREEN GLASS	Broken	1,357.00 FL	*1,357.00 FL
16	1		*FRONT WINDSCREEN OUTER MOULDING	Necessary	54.00 FL	*54.00 FL
17	1		*FRONT WINDSCREEN INNER DAM RUBBER	Necessary	48.00 FL	*48.00 FL
18	1		*FRONT WINDSCREEN ERP BRACKET STICKER	Necessary	15.00 FL	*15.00 FL
19	1		*FRONT WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
20	1		*FRONT WINDSCREEN SOLA FILM	Not Insured	360.00 FL	*- FL
21	1		*FRONT O/S WIPER ARM & BLADE RUBBER	Cut	146.00 FL	*146.00 FL
22	1		*FRONT N/S WIPER ARM & BLADE RUBBER	Cut	146.00 FL	*146.00 FL
23	1		*FRONT WIPER GARNISH	Serviceable	350.00 FL	*- FL
24	2		*FRONT O/S & N/S WIPER NOZZLE	Serviceable	38.00 FL	*- FL
25	1		*ROOF PANEL	Badly Dented	1,688.00 FL	*1,688.00 FL
26	1		*N/S ROOF PANEL TOP MOULDING	Twisted	102.00 FL	*102.00 FL
27	8		*N/S ROOF PANEL TOP MOULDING CLIPS HOLDER	Necessary	30.40 FL	*30.40 FL
28	1		*ROOF PANEL UPHOLSTERY	Serviceable	2,512.00 FL	*- FL
29	1		*N/S CENTRE DOOR PILLAR PANEL	Badly Dented	3,926.00 FL	*3,925.00 FL
30	1		*ROOF PANEL BODY SEALANT	Necessary	48.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,768.40	11,097.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,534.48	2,203.48
Total Parts (\$\$)	14,233.92	8,893.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE (BILL ENCLOSED)	New	60.00	60.00
2	TO REMOVE & REFIX FRONT WINDSCREEN GLASS & NECESSARY PARTS	New	160.00	120.00
3	TO REMOVE & REFIX ROOF PANEL UPHOLSTERY & PUMP SEALANT FOR ROOF PANEL	New	220.00	150.00
4	TO REMOVE & REFIX FRONT O/S & N/S DOOR INNER TRIM BOARD COVER,DOOR GLASS,REGULATOR,MOTOR,CHANNEL,WEATHERSTRIP,MOULDING & NECESSARY PARTS	New	260.00	60.00
5	TO REMOVE & REFIX CUSHION SEAT,DOOR PILLAR GARNISH,SAFETY BELT,CARPET,FLOOR MAT,DOOR RUN GARNISH & NECESSARY PARTS,TO ENABLE REPAIR ROOF PANEL,N/S CENTRE DOOR PILLAR,FRONT N/S DOOR PILLAR PANEL & NECESSARY PARTS	New	180.00	80.00
6	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	80.00	20.00
7	TO DIAGNOSE & RE-SET AIR-BAG FAULT CODE & SENSOR	New	150.00	0.00
8	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT FRONT N/S DOOR & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	2,300.00	1,800.00
9	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,500.00	1,600.00
Gross Labour Cost (\$\$)			5,910.00	3,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >