

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21000672/GVF3Q2  
**Date:** 22/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00099972000
Claimant Vehicle No :	SMG7950X	Insured Vehicle No :	SLS1314X
Date of Loss:	12/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200184/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG7950X	Engine No:	2AZ1A88110
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Chassis No:	JTEGD56M707166514
Reg. Date:	31/12/2018 (Man. Year: 2018)	Odometer:	27268 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,137.80	203.50	3,934.30	95.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,308.18	2,918.18	2,390.00	45.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,445.98</b>	<b>3,121.68</b>	<b>6,324.30</b>	<b>66.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>661.22</b>	<b>218.52</b>	<b>442.70</b>	<b>66.95</b>
<b>Nett Amount (S\$)</b>	<b>10,107.20</b>	<b>3,340.20</b>	<b>6,767.00</b>	<b>66.95</b>

### INSPECTION

Date of Assignment:	14/01/2021		
Date Inspected:	18/01/2021	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4 Singapore 408611
Estimated Period of Repair:	3.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2021)
<b>Parts:</b>	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG7950X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,RR BUMPER	Repair	596.90 FS	*- FS
2	1		*L/RR BUMPER SUPPORT	Not Necessary	40.40 FS	*- FS
3	1		*R/R SIDE BPR SUPPORT	Not Necessary	40.40 FS	*- FS
4	1		*CLIPS	Not Necessary	4.10 FS	*- FS
5	1		*ABSORBER,RR BUMPER	Not Necessary	79.60 FS	*- FS
6	1		*ABSORBER,RR BUMPER	Not Necessary	79.60 FS	*- FS
7	1		*PANEL LAMP LOWER	Repair	755.40 FS	*- FS
8	1		*PANEL SUB-ASSY,BACK	Repair	1,753.60 FS	*- FS
9	1		*EMBLEM	Necessary	72.20 FS	*72.20 FS
10	1		*PLATE,LUGGAGE	Necessary	44.10 FS	*44.10 FS
11	1		*PLATE,LUGGAGE	Necessary	57.20 FS	*57.20 FS
12	1		*SENSOR,ULTRASONIC	Not Necessary	392.80 FS	*- FS
13	1		*ANTENNA ELECTRICAL	Not Necessary	191.50 FS	*- FS
14	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>4,137.80</b>	<b>203.50</b>
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS	New	183.18	183.18
2	REMOVE & INSTALL REVERSE SENSOR TO ASSIST REPAIR	New	180.00	0.00
3	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	180.00	0.00
4	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR	New	360.00	360.00
5	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
6	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	2,160.00	720.00
7	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	2,065.00	1,475.00
Gross Labour Cost (S\$)			5,308.18	2,918.18

Report was unsubmitted during this print-out.

< END OF ESTIMATES >