

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI21000674/UTF3Q2

**Date:** 20/01/2021

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SKW9613X

**Insured Vehicle No :** XE5891B

Date of Loss: 12/01/2021

Nature of Claim: TP

Claim No: CDMFG21000075

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW9613X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRX540883

Reg. Date: 24/11/2015 (Man. Year: 2015)

Chassis No: MR053REH104542244

Colour: Silver

Odometer: 69130 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size:

205/55R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                   | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-----------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                   | 10,436.10         | 4,793.87          | 5,642.23          | 54.06         |
| Miscellaneous Items                     | 0.00              | 0.00              | 0.00              |               |
| Labour                                  | 2,890.00          | 1,710.00          | 1,180.00          | 40.83         |
| Paintwork Labour                        | 0.00              | 0.00              | 0.00              |               |
| Towing                                  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$)</b>      | <b>13,326.10</b>  | <b>6,503.87</b>   | <b>6,822.23</b>   | <b>51.19</b>  |
| <b>Approved Total (Overridden) (\$)</b> |                   | <b>5,200.00</b>   |                   |               |
| <b>Nett Amount (\$)</b>                 | <b>13,326.10</b>  | <b>5,200.00</b>   | <b>8,126.10</b>   | <b>60.98</b>  |

### INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021 Inspected At:

Choo Motor Spray Painter (HQ)

1 Kaki Bukit Avenue 6, #01-39

AutoBay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 19 Jan 2021)                  |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                              |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKW9613X)                                                                                                                                    |                                                                |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition      | Repairer's | Amount       |
|-----|-----|----------|---------------------------------------------|----------------|------------|--------------|
| 1   | 1   |          | *FRONT DOOR O/S                             | Badly Dented   | 1,422.10 F | *1,299.10 FL |
| 2   | 1   |          | *FRONT DOOR GLASS OUTER CHROME MOULDING O/S | Twisted        | 188.20 F   | *145.80 FL   |
| 3   | 1   |          | *FRONT DOOR INNER RUBBER O/S                | Necessary      | 239.50 F   | *211.20 FL   |
| 4   | 1   |          | *FRONT DOOR INNER TRIM BOARD O/S            | Not Necessary  | 988.10 F   | *- FL        |
| 5   | 1   |          | *SET FRONT DOOR FRAME BLACK STICKER O/S     | Necessary      | 90.00 F    | *80.00 FL    |
| 6   | 1   |          | *CENTRE PILLAR O/S                          | Bent           | 688.10 F   | *688.10 FL   |
| 7   | 1   |          | *REAR DOOR O/S                              | Badly Dented   | 1,399.20 F | *1,215.10 FL |
| 8   | 2   |          | *REAR DOOR HINGES                           | Twisted/Bent   | 210.00 F   | *210.00 FL   |
| 9   | 1   |          | *REAR DOOR CHECKER O/S                      | Twisted        | 166.20 F   | *148.60 FL   |
| 10  | 1   |          | *REAR DOOR GLASS OUTER CHROME MOULDING O/S  | Distorted      | 185.20 F   | *145.50 FL   |
| 11  | 1   |          | *REAR DOOR INNER RUBBER O/S                 | Necessary      | 239.50 F   | *210.00 FL   |
| 12  | 1   |          | *REAR DOOR INNER TRIM BOARD O/S             | Deformed/Torn  | 966.10 F   | *644.10 FL   |
| 13  | 1   |          | *REAR DOOR INNER LOCK O/S                   | Shorted/Jammed | 450.50 F   | *399.80 FL   |
| 14  | 1   |          | *REAR DOOR INNER LOCK INNER BRACKET O/S     | Cracked        | 288.10 F   | *211.20 FL   |
| 15  | 1   |          | *REAR DOOR GLASS REGULATOR & MOTOR O/S      | Bent/Jammed    | 545.10 F   | *450.00 FL   |
| 16  | 1   |          | *REAR DOOR OUTER HANDLE O/S                 | Serviceable    | 311.10 F   | *- FL        |
| 17  | 1   |          | *SET REAR DOOR FRAME BLACK STICKER O/S      | Necessary      | 90.00 F    | *80.00 FL    |
| 18  | 1   |          | *REAR FENDER O/S                            | Repair         | 1,219.10 F | *- FL        |
| 19  | 1   |          | *SET FRONT DOOR INNER TRIM BOARD CLIPS O/S  | Necessary      | 50.00 FS   | *50.00 FS    |
| 20  | 1   |          | *SET REAR DOOR INNER TRIM BOARD CLIPS O/S   | Necessary      | 50.00 FS   | *50.00 FS    |
| 21  | 1   |          | *SET DOOR VISOR                             | Necessary      | 100.00 FS  | *90.00 FS    |
| 22  | 1   |          | *REAR WINDSCREEN SEALANT                    | Not Necessary  | 50.00 FS   | *- FS        |
| 23  | 1   |          | *REAR SPORT RIM O/S                         | Not Necessary  | 500.00 FS  | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>10,436.10</b> | <b>6,328.50</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b> | <b>0.00</b>      | <b>1,534.63</b> |
| <b>Total Parts (\$\$)</b>                                 | <b>10,436.10</b> | <b>4,793.87</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                           |          |                 |                 |
| 1                               | TO CHECK WIRING                           | New      | 50.00           | 20.00           |
| 2                               | TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | New      | 120.00          | 80.00           |
| 3                               | TO TRANSFER BOTH DOOR MECHANISM           | New      | 120.00          | 120.00          |
| 4                               | TO CONDUCT WHEEL ALIGNMENT                | New      | 100.00          | 0.00            |
| 5                               | TO SPRAY RUST PROOFING                    | New      | 120.00          | 90.00           |
| 6                               | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 880.00          | 600.00          |
| 7                               | TO PUTTY & SPRAY PAINTING                 | New      | 1,500.00        | 800.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>2,890.00</b> | <b>1,710.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >