

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI21000677/GTF3Q2

**Date:** 25/01/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MS005340
<b>Claimant</b>	
<b>Vehicle No :</b> SHB2292E	<b>Insured Vehicle No :</b> GBD518D
Date of Loss: 13/01/2021	Nature of Claim: TP Claim No: M2100270

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2292E	Engine No:	2ZRS053273
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103560316
Reg. Date:	17/08/2017 (Man. Year: 2017)	Odometer:	516665 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,373.70	1,373.70	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	640.00	180.00	21.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,204.70</b>	<b>2,024.70</b>	<b>180.00</b>	<b>8.16</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,600.00</b>		
<b>(\$\$)</b>	2,204.70	1,600.00	604.70	27.43
<b>+ GST 7.00/7.00% (\$\$)</b>	154.33	112.00	42.33	27.43
<b>Nett Amount (\$\$)</b>	<b>2,359.03</b>	<b>1,712.00</b>	<b>647.03</b>	<b>27.43</b>

### INSPECTION

Date of Assignment:	14/01/2021 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/01/2021 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB2292E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	-	*458.60 FL
2	1		*REAR BUMPER CENTRE GUARD	Cut	552.60 FL	-	*552.60 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	-	*318.80 FL
4	1		*REAR BUMPER EXTENSION LH	Deformed	232.00 FL	-	*232.00 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REAR BUMPER MAT	Scratched	50.00 F	-	*50.00 F
7	1		*REVERSE SENSOR	Damaged	135.70 F	-	*135.70 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,769.70</b>	<b>1,769.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	396.00	396.00

<b>Total Parts (\$)</b>	<b>1,373.70</b>	<b>1,373.70</b>
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSOR	New	120.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>820.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >