



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103184

INV Date 06/05/2021

Reference CC4/LPC21000683/Abs3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 1972L
Insured Veh. YN 7527G
Claim No. 20/21/21/VC05/024135
Policy No. Z20VC05006070
Accident Date 12/01/2021
Inspection Date 15/01/2021

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21000683/Abs3q2 Date: 06/05/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7527G	Veh. Inspected	GBJ 1972L	
Policy No.	Z20VC05006070	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024135	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	14/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VM20122040	Colour	SILVER	
Odometer	34386 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	WINDFORCE	6 mm	
L/H Front Tyre	175/70 R14C	WINDFORCE	6 mm	
R/H Rear Tyre	175/70 R14C	WINDFORCE	6 mm	
L/H Rear Tyre	175/70 R14C	WINDFORCE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2021	Inspection Date	15/01/2021	
Survey held at	CHENG MOTOR WORK CO. NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1972L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP L/H (N)	CUT	477.60	477.60
1	FRONT HEADLAMP LOWER GARNISH (N)	DEFORMED	352.35	352.35
1	FRONT BUMPER (N)	CUT	573.60	573.60
1	FRONT BUMPER SIDE RETAINER (N)	NOT NECESSARY	32.80	-
1	FRONT GRILLE (N)	NOT NECESSARY	338.00	-
1	FRONT FENDER L/H (N)	DENTED	540.10	540.10
	LESS 10% DISCOUNT		-	-194.37
			2,314.45	1,749.28
	<u>LABOUR</u>			
	TO REPLACEMENT OF PARTS ,REPAIRING ,KNOCKING .		500.00	350.00
	TO SPRAY PAINT ON FENDER ,GARNISH ,BONNET .		550.00	250.00
	TO APPLY RUST-PROOFING .	NOT NECESSARY	80.00	-
	TO CHECK WIRING .		60.00	30.00
			1,190.00	630.00
	GRAND TOTAL		3,504.45	2,379.28
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CC4/LPC21000683/Abs3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 1972L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 1972L

RE-INSPECTION

