



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	TPVD MERCEDES (SMC2611D)
Date of Loss	11 January 2021
Time of Loss	19.05
Loss Description	SGS8900S (INSD) C/W REAR OF SMC2611D (TP)
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="48529"/>
Nett Loss Amount	\$15,471.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details

Vehicle Registration#	SMC2611D	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>05/09/2013</div> <div></div>
Mileage	<div>160439</div>	Age of Vehicle	7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2013</div>
Make	TPVD	<div>MERCEDES BENZ</div>
		<div></div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	BOEY LIH HAN	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	MERCEDES POLICY INFORMATION	E200 SEDAN (R17) ASSESSMENT INFORMATION
Type		<div></div>
Type of Paint		<div></div>
Chassis No		<div>WDD2120342A789005</div>
Engine No		<div>27492030055625</div>
Engine Capacity		<div>1991</div>
Sum Insured		<div>0</div>
Market Value		<div>64000</div>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<div></div>
Education Qualification	Other	<div></div>
Driving Experience	0	
Driver License #		<div></div>
License Type		<div></div>
License Issue Date		<div>dd/mm/yyyy</div> <div></div>
License Expiration Date		<div>dd/mm/yyyy</div> <div></div>

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

14/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts













Add







Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REVERSE SENSOR CENTRE - LH	Shorted	0	368	No		10			331.2	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID	Bent	0	2470	No		10			2223	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID CHROME MOULDING	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		SET REAR BOOT LID HINGE COVER CLIPS	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR LID HINGE COVER - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID HIBGE - LH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID EMBLEM - 7G-TRONIC	Necessary	0	85.2	No		10			76.68	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT LID MERCEDES STAR	Necessary	0	54	No		10			48.6	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID LAMP - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR EMBLEM 'E200'	Necessary	0	78	No		10			70.2	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID WEATHERSTRIP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER	Buckled	0	1698	No		10			1528.2	Reviewing
<input type="checkbox"/>		0	1		SET REAR BUMPER CLIPS	Necessary	0	80	No		10			72	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL GARNISH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILLAMP - LH	Cracked	0	685	No		10			616.5	Reviewing
<input type="checkbox"/>		0	1		REAR TAILLAMP - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER INNER GARNISH	Cracked	0	258	No		10			232.2	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER INNER IMPACT BRACKET	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER OUTER IMPACT BRACKET	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER BOTTOM BRACKET - LH	Damaged	0	85	No		10			76.5	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER BOTTOM BRACKET - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER SIDE MOULDING - LH	Necessary	0	137	No		10			123.3	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE MOULDING - RH	Necessary	0	137	No		10			123.3	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Bent	0	715	No		10			643.5	Reviewing



Labour


Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	0	550	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	0	660	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		COMPUTER DIAGNOSTIC	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO CHECK WIRING FUNCTIONS	0	20	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary







Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 5 DAYS	Reviewing		0		
<input type="checkbox"/>		0	REVERSE SENSOR CENTRE - RH	Deny		0	SERVICEABLE	
<input type="checkbox"/>		0	REVERSE SIDE SENSOR - LH	Deny		0	SERVICEABLE	

EDIT		SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	REVERSE SIDE SENSOR - RH	Deny		0	SERVICEABLE	
<input type="checkbox"/>		0	SET REAR REVERSE SENSOR WIRE	Deny		0	SERVICEABLE	
<input type="checkbox"/>		0	REAR BOOTLID CAMERA	Deny		0	SERVICEABLE	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$7,425.18	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$6,165.18			
Labour		\$0.00		\$1,260.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	5900		



Submit for Review